

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Foo Ai Ngoh

Date: 10 Mar 2023

Preliminary Advice

Vehicle No	: SLG8833G	Accident Date	: 10/02/2023
Make	: BMW X3 SDRIVE20I	Policy No.	: DMPG22017170
Assignment Date	: 28/02/2023	Excess	: S\$700.00
Date of Inspection	: 09/03/2023	Est. Duration of Repair	: 4 DAYS
Inspection At	: TLM AUTOMOTIVE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,404.20
Revised Amount	:S\$	5,895.00
Check Items (Estimated)	:S\$	11,524.00
Total	:S\$	17,419.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	185,000.00
COE / PARF Rebate	:S\$	75,718.00
Salvage Value	:S\$	
Margin for Repair	:S\$	109,282.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Part by Part repair.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.