

TLM Automobile Pte Ltd (Co.Reg.No:202244624K)

1 Defu Lane 6
Singapore 539365

Tel: 6858 5151 Email: accounts@tlmotor.com.sg

INSURER: ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD013022023
Policy No:	DMPG22017170	Date of Loss:	10/02/2023
Vehicle Reg. No.:	SLG8833G	Driveable?	
Driver Age/Info:	/ FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LOH WAI CHAN		
Driver:	LOH WAI CHAN		
Make/Model:	BMW X3 SDRIVE20I, 2.0 MSPT ADAPTIVE HL LED FL (A)	Vehicle Reg. Date:	29/12/2020
Vehicle Colour:	SILVER	Chassis No:	WBATS720409E42384
Engine No:	F152K428B48B20A		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	5.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Present Location:	TLM AUTOMOBILE PTE LTD (HQ)		

Not Applicable
her
Stress \$700
9/3/23
take photo before party -
4 days.

COST OF CLAIMS

	Amount
Parts	22,134.20
Miscellaneous Items	0.00
Labour	3,270.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	25,404.20
+ GST 8.00% (\$)	2,032.34
Nett Amount (\$)	27,436.54

This claim is handled by: JUSTIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

cost - 9360
+ 102
10286
860
11156

1st 10594.31
- 52
10444.59
860
11304.59

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, etc. resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Feb 2023)

Parts: M1-SUV BMW X3 SDRIVE20I 2.0 MSPT ADAPTIVE HL LED FL (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: TLM Automobile Pte Ltd/SLG8833G/27/02/2023 11:28

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	1440	*Front bumper <i>De/70.1</i>	5.00	0.00	*1,798.00 FL
2	2		*Front bumper side retainer <i>17</i>	5.00	0.00	*190.00 FL
3	1	150	*Front bumper lower <i>8.6-6</i>	5.00	0.00	*892.00 FL
4	1		*Front bumper towing cap <i>17</i>	5.00	0.00	*75.00 FL
5	2		*Front bumper sensor <i>17</i>	5.00	0.00	*596.00 FL
6	2		*Front bumper sensor seal <i>NS</i>	5.00	0.00	*70.00 FL
7	2		*Front bumper grille <i>2A 11</i>	5.00	0.00	*440.00 FL
8	1		*Front bumper grille inner bracket <i>17</i>	5.00	0.00	*95.00 FL
9	1		*Front bumper top rubber <i>17</i>	5.00	0.00	*112.00 FL
10	1	90	*Front bumper sponge <i>70.1</i>	5.00	0.00	*115.00 FL
11	1		*Front bumper reinforcement <i>R</i>	5.00	0.00	*950.00 FL
12	1		*Front bumper reinforcement cross <i>17</i>	5.00	0.00	*550.00 FL
13	2	4250	*Headlamp <i>N/S one 0/5 17</i>	5.00	0.00	*9,360.00 FL
14	2		*Headlamp lower bracket <i>17</i>	5.00	0.00	*500.00 FL
15	2		*Headlamp ballast <i>17</i>	5.00	0.00	*2,010.00 FL
16	1		*Front support panel (FIT) <i>R</i>	5.00	0.00	*278.00 FL
17	1		*Front support panel (REAR SECTION) <i>17</i>	5.00	0.00	*295.00 FL
18	1		*Aircon condenser <i>17</i>	5.00	0.00	*1,250.00 FL
19	1	2020	*Bonnet <i>3.11</i>	5.00	0.00	*2,150.00 FL
20	1	80	*Bonnet emblem <i>17</i>	5.00	0.00	*110.00 FL
21	1		*Front coolant assy <i>17</i>	5.00	0.00	*1,350.00 FL
22	1	15	*Front bumper clips <i>17</i>	0	0.00	*35.00 FS
23	10		*Front bumper lower clips <i>17</i>	0	0.00	*35.00 FS
24	5		*Front bumper grille clips <i>17</i>	0	0.00	*12.50 FS
25	10		*Bonnet insulator clips <i>17</i>	0	0.00	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,293.50
- List Item Discount on L Items (\$\$)	1,159.30
Total Parts (\$\$)	22,134.20

TLM Automobile Pte Ltd/SLG8833G/27/02/2023 11:28. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To check electrical lighting concerned.	New 20	120.00
2	To replace and remove front bumper sensor.	New 40	150.00
3	To conduct diagnostic check.	New 11	200.00 X
4	To replace, remove aircon condenser and refill aircon gas.	New 114	200.00 X
5	To replace and remove front coolant assy and refill coolant.	New 11	100.00 X
6	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New 400	1,200.00
7	Putty and spray painting of the affected portion.	New 400	1,300.00
Gross Labour Cost (S\$)			3,270.00

TLM Automobile Pte Ltd/SLG8833G/27/02/2023 11:28. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

460

< END OF ESTIMATES >

TLM Automobile Pte Ltd (Co.Reg.No:202244624K)

1 Defu Lane 6
Singapore 539365

Tel: 6858 5151 Email: accounts@tlmotor.com.sg

(SUPPLEMENTARY)

INSURER: ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD013022023
Policy No:	DMPG22017170	Date of Loss:	10/02/2023
Vehicle Reg. No.:	SLG8833G	Driveable?	
Driver Age/Info:	/ FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LOH WAI CHAN		
Driver:	LOH WAI CHAN		

Make/Model:	BMW X3 SDRIVE20I, 2.0 MSPT ADAPTIVE HL LED FL (A)	Vehicle Reg. Date:	29/12/2020
Vehicle Colour:	SILVER		
Engine No:	F152K428B48B20A	Chassis No:	WBATS720409E42384
Odometer:	0 KM		

Paint Type:	
List Item Discount:	5.00 %
Total Loss?	NO
Est. Duration of Repair (day)	0

Present Location: TLM AUTOMOBILE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	1,153.59
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,153.59
+ GST 8.00% (S\$)	92.29
Nett Amount (S\$)	1,245.88
+ Previous Estimates (S\$)	27,436.54
Claim Total (S\$)	28,682.42

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 30 Mar 2023)**Parts:** M1-SUV BMW X3 SDRIVE20I 2.0 MSPT ADAPTIVE HL LED FL (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLG8833G)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount
1	2	180 x 2 = 360	*2PCS FRONT GRILLE	CNO	5.00	0.00	*811.56 FL ✓
2	1	245	*1PC FRONT GRILLE INNER BRACKET	CNO	5.00	0.00	*270.25 FL ✓
3	1	110	*1PC AIR GUIDE radiator top	TOIN	5.00	0.00	*132.50 FL ✓
F=Franchise part, L=ListItemDisc.							
Sub Total (S\$)							1,214.31
- List Item Discount on L Items (S\$)							60.72
Total Parts (S\$)							1,153.59

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**