

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT
 #01-49 SINGAPORE 415875
 Tel: +65 64524457
 Fax: +65 64524584
 Company Reg No: 201929175W

Repair Estimate

Vehicle number: SJN8779S
 Make & Model: Nissan Qashqai
 Chassis number: SJNFBAJ11U2012182

Date of survey:
 Name of surveyor:
 Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Tailgate <i>paint</i> ✓	1	\$ 2936 ✓ 3,062.50
2	Tailgate windscreen glass rubber moulding <i>NCC</i>	1	\$ 150.50 ✓
3	Tailgate outer garnish <i>X nn</i>	1	\$ 337.90
4	Tailgate outer garnish clips <i>X nn</i>	1set	\$ 70.00
5	Tailgate centre emblem <i>X nn</i>	1	\$ 79.90
6	Tailgate "Qashqai" emblem <i>NCC</i> ✓	1	\$ 87.00 ✓
7	Tailgate inner trim board <i>X nn</i>	1	\$ 357.80
8	Tailgate inner trim board clips <i>X nn</i>	1	\$ 80.00
9	Tailgate lock <i>X nn</i>	1	\$ 173.30
10	Tailgate lock catch <i>X nn</i>	1	\$ 45.50
11	Tailgate RH lamp <i>X nn</i>	1	\$ 367.40
12	Tailgate RH lamp gasket <i>X nn</i>	1	\$ 22.00
13	Tailgate LH lamp <i>X nn</i>	1	\$ 367.40
14	Tailgate LH lamp gasket <i>X nn</i>	1	\$ 22.00
15	Tailgate weatherstrip <i>X nn</i>	1	\$ 188.20
16	Tailgate wiper motor <i>X nn</i>	1	\$ 655.20
17	Rear bumper <i>Br</i>	1	\$ 765.40 ✓
18	Rear bumper clips <i>NCC</i>	1set	\$ 80.00 30 ✓
19	Rear bumper RH reflector <i>X nn</i>	1	\$ 65.70
20	Rear bumper LH reflector <i>X nn</i>	1	\$ 65.70
21	Rear bumper towing cover <i>X nn</i>	1	\$ 28.00
22	Rear bumper reinforcement <i>X nn</i>	1	\$ 621.80
23	Rear bumper reinforcement LH bracket <i>X nn</i>	1	\$ 166.20
24	Rear bumper reinforcement RH bracket <i>X nn</i>	1	\$ 166.20
25	Rear bumper LH side retainer <i>X nn</i>	1	\$ 47.80
26	Rear bumper RH side retainer <i>X nn</i>	1	\$ 47.80
27	Rear bumper inner sponge <i>Br</i>	1	\$ 142.00 ✓
28	RH taillamp assy <i>X nn</i>	1	\$ 415.60
29	RH taillamp gasket <i>X nn</i>	1	\$ 24.00
30	RH taillamp lock clips <i>X nn</i>	1set	\$ 18.00
31	RH taillamp panel <i>X nn</i>	1	\$ 133.20
32	LH taillamp assy <i>X nn</i>	1	\$ 415.60
33	LH taillamp gasket <i>X nn</i>	1	\$ 24.00
34	LH taillamp lock clips <i>X nn</i>	1set	\$ 18.00
35	LH taillamp panel <i>X nn</i>	1	\$ 133.20
36	End panel <i>BVC</i>	1	\$ 553.20 ✓
37	End panel inner garnish <i>rm</i>	1	\$ 83.30 ✓
38	End panel inner garnish clips <i>NCC</i>	1set	\$ 70.00 15 ✓
39	Rear RH fender inner trim board <i>X nn</i>	1	\$ 404.70
40	Rear RH fender inner trim board clips <i>X nn</i>	1set	\$ 70.00
41	Rear RH fender splash shield <i>X nn</i>	1	\$ 118.90
42	Rear RH fender splash shield clips <i>X nn</i>	1set	\$ 70.00
43	Rear LH fender inner trim board <i>X nn</i>	1	\$ 404.70
44	Rear LH fender inner trim board clips <i>X nn</i>	1set	\$ 70.00
45	Rear LH fender splash shield <i>X nn</i>	1	\$ 118.90

46	Rear LH fender splash shield clips	X nn	1set	\$	70.00
47	Rear floor panel top cover board	X nn	1	\$	456.20
48	Rear floor panel side tray garnish RH	X nn	1	\$	247.10
49	Rear floor panel side tray garnish LH	X nn	1	\$	247.10
50	Rear floor panel sponge tray LH	X nn	1	\$	99.10
51	Rear floor panel sponge tray RH	X nn	1	\$	99.10
52	Exhaust silencer heat shield	X nn	1	\$	178.00
53	Exhaust silencer	X nn	1	\$	783.90
54	Exhaust silencer gasket	X nn	1	\$	56.00

4762.40
-10%
4286.16

Parts less 10%	\$	13,645.00
Total	\$	12,280.50

No.	Special Nett Items	Qty	Amount S\$
1	Tailgate windscreen glass sealant nec	1	\$ 80.00
2	Tailgate windscreen glass inner seal nec	1	\$ 60.00
3	Tailgate chrome moulding X nn	1	\$ 450.00
4	Tailgate reverse camera X nn	1	\$ 750.00
5	End panel joint sealant nec	1	\$ 80.00
6	Rear bumper reverse sensor (4 sensors) MALfunction	1	\$ 380.00
7	Rear number plate X nn	1	\$ 80.00

Total: \$ 1,880.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 400 1,600.00
2	Spray painting on affected areas and panels	\$ 600 1,400.00
3	Check wiring and lighting system on affected areas	\$ 30 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 30 100.00
5	Remove and reinstall tailgate windscreen glass to assist repair	\$ 80 220.00
6	Remove and replace tailgate reverse camera to assist repair	\$ 30 100.00
7	Remove and replace tailgate inner mechanism to new tailgate	\$ 30 180.00
8	Remove and replace rear bumper reverse sensors (4 sensors)	\$ 30 150.00
9	Remove and replace rear inner board, garnish and trims to assist repair	\$ 60 280.00
10	Remove and replace exhaust silencer and gasket to assist repair	\$ X 180.00

Total: \$ 4,290.00

5896.16

L/S - 4716.92
= 4700

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

4 days
L/S
9/10/23 11/3/23 4:30pm

Spare Parts:	\$	12,280.50
Special Nett:	\$	1,880.00
Labour:	\$	4,290.00

Total Amount: \$ 18,450.50

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: