

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS

VEHICLE NO : PC7868L
VEHICLE MODEL : HIGER KLQ6128K
CHASSIS NO : LKLR1LSL3JA738017

TP China.
Veron.

CLAIM DETAILS: PARTS

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	LUGGAGE COMPARTMENT COVER Buckled	1	\$ 2,500.00	\$ 2,500.00
2	LUGGAGE COMPARTMENT COVER HANDLE gm	1	\$ 150.00	\$ 150.00
3	LUGGAGE COMPARTMENT COVER HANDLE REFLECTOR gm	1	\$ 100.00	\$ 100.00
4	UTILITY COMPARTMENT COVER Buckled	1	\$ 1,200.00	\$ 1,200.00
5	REAR WHEEL PANEL Buckled	1	\$ 1,500.00	\$ 1,500.00
6	REAR WHEEL RIM COVER Xtem	1	\$ 300.00	\$ 300.00

TOTAL : \$ 5,750.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	600	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	800	
3	TO APPLY TUFF COAT	\$ 200.00	40	

TOTAL: \$ 2,600.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 5,750.00
TOTAL LABOUR COST: \$ 2,600.00
TOTAL REPAIR COST: \$ 8,350.00

total: 4640

4/s: 3.7K

04 Days

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:
NO. OF DAYS:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3.7K