

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SLV2040M

No. Qty

Nett Items

- | | | |
|---|---|---------------------------------|
| 1 | 1 | Rear bumper |
| 2 | 1 | Rear bumper RH tow cover |
| 3 | 2 | Rear bumper reflector |
| 4 | 2 | Rear bumper side retainer |
| 5 | 1 | Rear bumper inner foam |
| 6 | 1 | Rear bumper inner reinforcement |

<i>Net/bm</i>	\$	787.00	✓
	\$	<i>nw</i> 27.00	✓
	\$	<i>pl</i> 123.40	X
	\$	<i>pl</i> 94.60	X
	\$	126.40	7
	\$	619.00	7
	\$	1,777.40	
Less 10%	\$	177.74	
Total :	\$	1,599.66	

Special Nett Items

- 7 1 set Reverse sensors

\$ *Net* 400.00 *2001*

Labour

- | | |
|---|---|
| 1 | Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages. |
| 2 | To putty and spray Spray Paintings charges. |
| 3 | To check wirings & lightings. |
| 4 | To remove, refix & reset reverse sensors. |
| 5 | To supply and apply anti rust treatment. |

\$	600.00	<i>30d</i>
\$	600.00	<i>48d</i>
\$	40.00	<i>10L</i>
\$	80.00	<i>50L</i>
\$	<i>nw</i> 60.00	X
Total :	\$	1,380.00

Total Parts and Labour : \$ 3,379.66

Not Withnile
Resurvey B & Party
3days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: