

Date : 15.12.2022

To : **LKK**

Fax :

Attn : **TAUFIKH**

Vehicle Reg No. : **SHA4868L**

23.11.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: **CHINA** **SBR118B**

2. The finalized amount shall be:

(a)	Spare Parts after List discount	100
-----	---------------------------------	-----

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost	\$10,850.00
----------------------------------	--------------------

3. Estimated normal period for repairs: **5** working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature: 

Name : CHIANG

Name : Taufikh

Tel : 62148314

Date : 28/2/23

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

[illegible]

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 15.12.2022
Time: 14:43:52
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305537657
REGN NO : SHA4868L
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 30.05.2017
DATE/TIME IN : 23.11.2022 20:50
ACCIDENT DATE : 23.11.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2292-A	COVER FRONT BUMPER+#	1	0.00	0.00	0.00
0002	04-01-0302-2298-G	REINFORCEMENT SUB-ASSY FR	1	0.00	0.00	0.00
0003	04-01-0302-2164-A	GRILLE SUB-ASSY RADIATOR+	1	0.00	0.00	0.00
0004	04-01-0302-2062-G	GRILLE RADIATOR LOWER NO.	1	0.00	0.00	0.00
0005	04-01-0302-0632-G	COVER FRONT BUMPER HOLE L	1	0.00	0.00	0.00
0006	04-01-0302-0633-G	COVER FRONT BUMPER HOLE R	1	0.00	0.00	0.00
0007	04-01-0302-2267-G	BUMPER PIECE	10	0.00	0.00	0.00
0008	04-01-0302-2170-G	BRACKET FRT BUMPER EXTENS	1	0.00	0.00	0.00
0009	04-01-0302-0572-A	HOOD SUB-ASSY+#	1	0.00	0.00	0.00
0010	04-01-0302-0988-G	EMBLEM ASSY RADIATOR GRIL	1	0.00	0.00	0.00
0011	04-01-0302-2815-A	UNIT ASSY HEADLAMP LH#	1	0.00	0.00	0.00
0012	04-01-0302-2915-A	UNIT ASSY HEADLAMP RH#	1	0.00	0.00	0.00
0013	04-01-0302-2282-A	COVER REAR BUMPER+#	1	0.00	0.00	0.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305537657
 REGN NO : SHA4868L
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID
 DATE OF REGN : 30.05.2017
 DATE/TIME IN : 23.11.2022 20:5
 ACCIDENT DATE : 23.11.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014	04-01-0302-2287-G	GUARD-REAR BUMPER CENTER	1	0.00	0.00	0.00
0015	04-01-0302-2347-G	COVER REAR FLOOR	1	0.00	0.00	0.00
0016	04-01-0302-2267-G	BUMPER PIECE	10	0.00	0.00	0.00
0017	04-01-0302-1150-A	BUMPER PROTECTOR MAT	1	0.00	0.00	0.00
0018	09-01-0302-2005-A	REVERSE SENSOR ASSY XX	1	0.00	0.00	0.00
0019	28-01-0302-2028-A	VEHICLE NUMBER PLATE FRON	1	0.00	0.00	0.00
0020	04-01-0302-2402-G	LOCK ASSY HOOD	1	0.00	0.00	0.00
0021	04-01-0302-0635-G	ABSORBER FRONT BUMPER ENE	1	0.00	0.00	0.00
0022	04-01-0302-0574-A	FENDER SUB-ASSY FRONT LH+	1	0.00	0.00	0.00
0023	04-01-0302-4891-A	LAMP ASSY FOG LH	1	0.00	0.00	0.00
0024	04-01-0302-2277-A	SUPPORT SUB-ASSY RADIATOR	1	0.00	0.00	0.00
0025	04-01-0302-2875-G	SUPPORT SUB-ASSY RADIATOR	1	0.00	0.00	0.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305537657
 REGN NO : SHA4868L
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID
 DATE OF REGN : 30.05.2017
 DATE/TIME IN : 23.11.2022 20:5
 ACCIDENT DATE : 23.11.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0026 04-01-0302-2975-G	SUPPORT SUB-ASSY RADIATOR	1	0.00	0.00	0.00
0027 04-01-0302-2301-G	SUP SUB-ASSY RADIATOR LOW	1	0.00	0.00	0.00
0028 02-01-0302-2075-G	INLET AIR CLEANER NO.3	1	0.00	0.00	0.00
0029 04-01-0302-2871-G	SUPPORT FRONT BUMPER SIDE	1	0.00	0.00	0.00
0030 04-01-0302-2872-A	HINGE ASSY HOOD LH+	1	0.00	0.00	0.00
0031 04-01-0302-2972-A	HINGE ASSY HOOD RH+	1	0.00	0.00	0.00
0032 04-01-0302-2297-G	EMBLEM SIDE PANEL (HYBRID	1	0.00	0.00	0.00
0033 01-01-0302-2039-G	CONDENSER ASSY	1	0.00	0.00	0.00

SUB-TOTAL : 0.00

JOB NATURE

0000 PB LUMP SUM SHA4868L TP 10850.00

SUB-TOTAL : 10,850.00