

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI23002187/TNY3Q2**Date:** 19/04/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MAA00096	
<b>Claimant Vehicle No :</b>	SHA2275K	<b>Insured Vehicle No :</b>	SLN7684P	
Date of Loss:	25/02/2023	Nature of Claim:	TP	Claim No: M2301315

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHA2275K</b>	Engine No:	2ZR2B83524
Make & Model:	TOYOTA PRIUS, 1.5 HYBRID (A)	Chassis No:	JTDKB3FU303077670
Reg. Date:	13/12/2018 (Man. Year: 2018)	Odometer:	423798 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	907.52	280.00	627.52	69.15
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,970.00	1,275.00	695.00	35.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,888.52</b>	<b>1,566.00</b>	<b>1,322.52</b>	<b>45.79</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>231.08</b>	<b>125.28</b>	<b>105.80</b>	<b>45.79</b>
<b>Nett Amount (S\$)</b>	<b>3,119.60</b>	<b>1,691.28</b>	<b>1,428.32</b>	<b>45.79</b>

INSPECTION

Date of Assignment:	01/03/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	28/02/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Apr 2023)
Parts:	144	TOYOTA PRIUS 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA2275K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER RH	Repair	836.70 FL	*- FL
2	1		*REAR DOOR COMFORT APPS LOGO RH	Necessary	80.00 F	*80.00 F
3	1		*RENEW ADVERTISEMENT STICKER	Cut	200.00 F	*200.00 F
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	1,116.70 280.00
					- List Item Discount on L Items 25.00/25.00% (S\$)	209.18 0.00
					Total Parts (S\$)	907.52 280.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,050.00	525.00
2	SPRAY PAINTING CHARGE	New	800.00	750.00
3	REMOVE/ REFIX UPHOLSTERY REAR	New	120.00	0.00
Gross Labour Cost (\$\$)			1,970.00	1,275.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >