

SV0 23008638

TD 13/3/23



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : ALLIANZ INSURANCE SINGAPORE PTE LTD
12 MARINA VIEW
#04-01, ASIA SQUARE TOWER 2
SINGAPORE 018961

Registration No : SMQ8749C

Chassis No : JHMRU1810JX201855

Model : HRV DX-SIN CVT YM 2018

Owner's Name : KHOO YEE HONG

Ins Policy No. :
YJ

Date of Accident : 25/2/2023

Document No. : SQT23000592 Page 1

Date : 27. Feb 2023

Customer No. : WZA011

Svc Advisor : YOU PO SOON

Engine No : L15B5671857

Date | Time : 27. Feb 2023 12:40:54 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER <i>NEL</i>	1	19.30 ✓	25	14.47	1.16	15.63 ✓
73226-SZW-000	DAMPERSTD 5X5 <i>NEL</i>	1	9.10 ✓	25	6.82	0.55	7.37 ✓
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER <i>NEL</i>	1	19.30 ✓	25	14.47	1.16	15.63 ✓
76711-T6A-003	CAPPIVOT <i>NEL</i> X nn	1	5.20 ✓	25	3.90	0.31	4.21
91501-S70-003	FASTENER BW/SHIELD <i>NEL</i>	4	5.30 ✓	25	15.90	1.27	17.17 ✓
91502-S70-003	FASTENER B <i>NEL</i>	2	5.40 ✓	25	8.10	0.65	8.75 ✓
91536-SS0-J01	FASTENER AW/SHIELD <i>NEL</i>	2	3.80 ✓	25	5.70	0.46	6.16 ✓
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>NEL</i>	1	60.00		120.00	9.60	129.60 ✓
68100-T7A-J20ZZ	TAIL GATE COMP <i>BUC</i>	1	915.90 ✓	25	686.92	54.95	741.87 ✓
84431-T7A-J01ZA	LINING ASSYTAILGATE <i>XNN</i>	1	145.60	25	109.20	8.74	117.94
84441-S2K-000ZB	POCKETTAILGATE PULL <i>XNN</i>	1	16.20	25	12.15	0.97	13.12
75722-T7W-A01	EMBLEMRR <i>NEL</i>	1	15.40 ✓	25	11.55	0.92	12.47 ✓
75725-T8N-T00	EMBLEM,RR. I-VTEC <i>NEL</i>	1	16.70 ✓	25	12.52	1.00	13.52 ✓
75701-T4G-000	EMBLEM <i>NEL</i>	1	25.90 ✓	25	19.42	1.55	20.97 ✓
90301-ST0-003	NUT,PUSH 3MM <i>NEL</i> X nn	2	2.10 ✓	25	3.15	0.25	3.40 ✓
74440-T7A-003	WEATHERSTRIPTAILGATE <i>NEL</i> X nn	1	105.60	25	79.20	6.34	85.54
74800-T7Y-K01	LOCK ASSY,TAILGATE ASSY <i>NEL</i> X nn	1	174.70	25	131.02	10.48	141.50
66100-T7A-300ZZ	PANEL COMPRR. <i>BUC</i>	1	399.40 ✓	25	299.55	23.96	323.51 ✓
04655-T7A-310ZZ	PANEL SET,RR.FLOOR <i>NEL</i> X nn	1	723.00	25	542.25	43.38	585.63

Printed on 27/2/2023 1:02:44 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

2/3/23 2:00pm

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : ALLIANZ INSURANCE SINGAPORE PTE LTD
12 MARINA VIEW
#04-01, ASIA SQUARE TOWER 2
SINGAPORE 018961

Registration No : SMQ8749C

Chassis No : JHMRU1810JX201855

Model : HRV DX-SIN CVT YM 2018

Owner's Name : KHOO YEE HONG

Ins Policy No. :

Date of Accident : 25/2/2023

Document No. : SQT23000592 **Page** 2

Date : 27. Feb 2023

Customer No. : WZA011

Svc Advisor : YOU PO SOON

Engine No : L15B5671857

Date | Time : 27. Feb 2023 12:40:54 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
65513-T7A-300ZZ	STIFFENERRR.JACK UP WEL nn	1	65.70	25	49.27	3.94	53.21
65750-T5B-300ZZ	CROSSMEMBER COMPRR.FLOOR WEL nn	1	96.60	25	72.45	5.80	78.25
04715-T7A-900ZZ	FACE,RR.BUMPER denx	1	484.70 ✓	25	363.52	29.08	392.60 ✓
04717-T7A-J00ZZ	FACE,R.RR.BUMPER CORNER X nn	1	100.80	25	75.60	6.05	81.65
04718-T7A-J00ZZ	FACE,L.RR.BUMPER CORNER X nn	1	100.80	25	75.60	6.05	81.65
91505-TM8-003	CLIP,BUMPER wel	25	2.30 ✓	25	43.12	3.45	46.57 ✓
34150-T7A-J31	LIGHT ASSY,R.LID X nn	1	288.90	25	216.67	17.33	234.00
34155-T7A-J31	LIGHT ASSY,L.LID X nn	1	288.90	25	216.67	17.33	234.00
33502-T7A-J31	LAMP UNIT,R. X nn	1	429.90	25	322.42	25.79	348.21
33552-T7A-J31	LAMP UNIT,L. X nn	1	429.90	25	322.42	25.79	348.21
74940-TZ5-A01	BUZZER ASSYSMART ? X nn	1	64.70	25	48.52	3.88	52.40
38387-TZ5-A01	ANTENNA ASSYL.F. X nn	1	63.50	25	47.62	3.81	51.43
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR X nn	1	203.10	25	152.32	12.19	164.51
84550-T7A-J10	BOX ASSY,CARGO FL X nn	1	138.60	25	103.95	8.32	112.27
84640-T7A-J01ZA	LINING ASSYRR.PANEL nn Br ✓	1	47.00 ✓	25	35.25	2.82	38.07 ✓
84610-T7A-J01ZA	BASE COMPR.TRUNK SIDE LINING X nn	1	157.40	25	118.05	9.44	127.49
84660-T7A-J02ZA	BASE COMP,L.TRUNK SIDE LINING X nn	1	145.40	25	109.05	8.72	117.77
04711-T7A-J00ZZ	FACE,FR.BUMPER Sur R X	1	509.00	25	381.75	30.54	412.29
71140-T7A-J00	BEAM,R.FR.BUMPER UPPER ? X nn	1	33.90	25	25.42	2.03	27.45
71130-T7A-J00ZZ	BEAM COMP,FR.BUMPER ? X nn	1	260.40	25	195.30	15.62	210.92
71193-T7A-J00	SPACER,R.FR.BUMPER SIDE wel nn	1	11.80	25	8.85	0.71	9.56
71198-T7A-J00	SPACER,L.FR.BUMPER SIDE X nn	1	11.80	25	8.85	0.71	9.56
71102-T7A-J20	FACE,FR.BUMPER LOWER X nn	1	347.20	25	260.40	20.83	281.23
71121-T7A-G01	BASE,FR.GRILLE X nn	1	234.00	25	175.50	14.04	189.54
71122-T7A-J01	MOLDING,FR.GRILLE UPPER X nn	1	227.80	25	170.85	13.67	184.52
75700-T5A-000	EMBLEM H X nn	1	17.40	25	13.05	1.04	14.09
90301-ST0-003	NUT,PUSH 3MM X nn	2	2.10	25	3.15	0.25	3.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) X nn	2	45.00		90.00	7.20	97.20
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ? X nn	1	320.00		320.00	25.60	345.60

Printed on 27/2/2023 1:02:44 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : ALLIANZ INSURANCE SINGAPORE PTE LTD
12 MARINA VIEW
#04-01, ASIA SQUARE TOWER 2
SINGAPORE 018961
Registration No : SMQ8749C
Chassis No : JHMRU1810JX201855
Model : HRV DX-SIN CVT YM 2018
Owner's Name : KHOO YEE HONG
Ins Policy No. :
Date of Accident : 25/2/2023

Document No. : SQT23000592 Page 3
Date : 27. Feb 2023
Customer No. : WZA011
Svc Advisor : YOU PO SOON
Engine No : L15B5671857
Date | Time : 27. Feb 2023 12:40:54 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount Incl GST
72841-SH3-315	OILSHEET WCC X NN	1	43.50	25	32.62 X	2.61	35.23
Sum Item					6154.53	492.34	6,646.87
BOSUN	SUNDRIES	1	50.00	20 ✓	50.00	4.00	54.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	160 ✓	180.00	14.40	194.40
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	200.00	✓	200.00	16.00	216.00
BOJSE	BODY JOINT SEALANT.	1	200.00	100 ✓	200.00	16.00	216.00
BOBC	BODY UNDERSIDE COATING (N)	1	200.00	150 100 ✓	200.00	16.00	216.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	450.00	350 250 ✓	450.00	36.00	486.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00	450 ✓	650.00	52.00	702.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00	350 ✓	450.00	36.00	486.00
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00	350 ✓	450.00	36.00	486.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00	540 ✓	650.00	52.00	702.00
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00	650 ✓	650.00	52.00	702.00
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	650.00	450 X	650.00	52.00	702.00
BMI02D	REMOVE & INSTALL RR SEATS LININGS GARNISHES & ETC.	1	650.00	450 X	650.00	52.00	702.00
BKOT00R	RENEW RR FLOOR INSULATOR.(N)	1	450.00	250 X	450.00	36.00	486.00
BMU30R	REMOVE & INSTALL EXHAUST SYSTEM.(N)	1	450.00	X	450.00	36.00	486.00
BKRP02B	CUT & RENEW RR FLOOR PANEL.STRAIGHTEN FENDERS ALIG	1	5500.00	4550 3900 ✓	5500.00	440.00	5940.00
BP07R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P)	1	3800.00	3120 ✓	3800.00	304.00	4104.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00	X	180.00	14.40	194.40
BKKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	1500.00	650	1500.00	120.00	1620.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1200.00	520	1200.00	96.00	1296.00
Sum Labor					18510.00	1,480.80	19,990.80

Printed on 27/2/2023 1:02:44 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

9 1-2 days
P/P
130pm
90097659
11fen
2/3/23

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: ALLIANZ INSURANCE SINGAPORE PTE LTD	Document No.	: SQT23000592	Page	4
	12 MARINA VIEW	Date	: 27. Feb 2023		
	#04-01, ASIA SQUARE TOWER 2	Customer No.	: WZA011		
	SINGAPORE 018961	Svc Advisor	: YOU PO SOON		
Registration No	: SMQ8749C	Engine No	: L15B5671857		
Chassis No	: JHMRU1810JX201855	Date Time	: 27. Feb 2023 12:40:54 PM		
Model	: HRV DX-SIN CVT YM 2018	Surveyor Name	:		
Owner's Name	: KHOO YEE HONG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 25/2/2023				

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
Survey By							
Date & Time							
Excess							
Status							
Signature							
					Total Amount	24,664.53	1,973.14
					Total (Inclusive of GST)		26,637.67

Printed on 27/2/2023 1:02:44 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53,50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.