

18/3
WD: 9 Days1/2
SERVICE PRE-INVOICEKAH MOTOR CO. SDN. BHD. AHU: IRFAN.
(A Member of the Oriental Holdings Berhad)GST Reg No.: M200050223
Company Ref. No.: S60FC1380G370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:	CU0097267 / ALLIANZ	Document No:	SVO23008638
Chassis No:	JHMRU1810JX201855	Printed By:	PSYOU
License No:	SMQ8749C	Order Date:	2. March 2023
Mileage:	17738	Order Time:	1:31:33 PM
Engine No:	L15B5671857	Service Advisor:	YOU PO SOON

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	8% GST Amount incld	Amount	GST
	TP DIRECT SETTLEMENT (J/NO: 78189)							
	OWNER: MS KHOO							
	OWNER INSURER: T/MARINE							
	ACC DATE: 25/2/2023							
	SURVEYED BY: IRFAN							
	DATE: 2/3/2023							
	REF NO:							
	TP INSURER: ALLIANZ							
	TP VEH: SMU8473B							
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.16	15.63	
73226-SZW-000	DAMPERSTD 5X5	1	9.10	25	6.82	0.55	7.37	
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.16	15.63	
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.27	17.17	
91502-S70-003	FASTENER B	2	5.40	25	8.10	0.65	8.75	
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.46	6.16	
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.80	64.80	
68100-T7A-J20ZZ	TAIL GATE COMP	1	915.90	25	686.92	54.95	741.87	
75722-T7W-A01	EMBLEMRR.	1	15.40	25	11.55	0.92	12.47	
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	16.70	25	12.52	1.00	13.52	
75701-T4G-000	EMBLEM	1	25.90	25	19.42	1.55	20.97	
90301-ST0-003	NUT,PUSH 3MM	2	2.10	25	3.15	0.25	3.40	
66100-T7A-300ZZ	PANEL COMPRR.	1	399.40	25	299.55	23.96	323.51	
04715-T7A-900ZZ	FACE,RR.BUMPER	1	484.70	25	363.52	29.08	392.60	
91505-TM8-003	CLIP,BUMPER	25	2.30	25	43.12	3.45	46.57	
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	47.00	25	35.25	2.82	38.07	
	SUM PARTS:				1,600.46	128.03	1,728.49	
BOSUN	0760	1	20.00		20.00	1.60	21.60	
	SUNDRIES							
BML02I	0760	1	160.00		160.00	12.80	172.80	
	INSPECT RR LIGHTING MECHANISMS.							
	PERFORM WATER							
	TEST.(N)							
BA02R	EXT-YJ	1	200.00		200.00	16.00	216.00	
	REMOVE & INSTALL REVERSE							
	SENSORS-4 PCS (N)							
BOJSE	0760	1	100.00		100.00	8.00	108.00	
	BODY JOINT SEALANT.							
BOBC	EXT-YBH	1	100.00		100.00	8.00	108.00	
	BODY UNDERSIDE COATING (N)							
BP00R	EXT-YBH	1	250.00		250.00	20.00	270.00	
	APPLY BODY UNDERSIDE COATING (N).							
BMI03D	EXT-YJ	1	450.00		450.00	36.00	486.00	
	REMOVE & INSTALL REAR							
	COMPARTMENT LININGS							
	GARNISHES.(N)							
BC012R	1931	1	350.00		350.00	28.00	378.00	
	RESET VEHICLE SMART ENTRY							
	SYSTEM							
BC011R	1931	1	350.00		350.00	28.00	378.00	
	REMOVE INSTALL & CALIBRATE REAR							
	VIEW CAMERA							

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0097267 / ALLIANZ
Chassis No: JHMRU1810JX201855
License No: SMQ8749C
Mileage: 17738
Engine No: L15B5671857

Document No: SVO23008638
Printed By: PSYOU
Order Date: 2. March 2023
Order Time: 1:31:33 PM
Service Advisor: YOU PO SOON

BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	540.00	540.00	43.20	583.20
BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N)	1	650.00	650.00	52.00	702.00
BKRP02B	EXT-YJ CUT & RENEW RR PANEL. STRAIGHTEN FLOOR ALIGN RR CHASSIS INCLUDING FITTING ON ATTACHMENT ITEMS.	1	3,900.00	3,900.00	312.00	4,212.00
BP07R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(6P)	1	3,120.00	3,120.00	249.60	3,369.60
BKBH01S	EXT-YJ STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	650.00	650.00	52.00	702.00
BP02R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(1P)	1	520.00	520.00	41.60	561.60
			SUM LABOUR:	11,360.00	908.80	12,268.80
			TOTAL SGD	12,960.46	1,036.83	13,997.29

Total Payable (SGD)**13,997.29**

GST Amount is calculated from individual line(s)