

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0211/2023/EQ
DATE : 25-Feb-23
WIP : 64965

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/2/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR PALLVI D/O NARENDRALAL NANALAL MEHTA
ADDRESS : 72 BAYSHORE ROAD
#27-13
SINGAPORE 469988
TELEPHONE : HP +65 92988116
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900156323-01
VEHICLE NO : **SMN 8824 J**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI
MODEL YEAR : 30/8/2019
ENGINE NO : DAX 056963
CHASSIS NO : WAUZZZF5K2108343
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Feb-23
PLACE OF ACCIDENT : ESSO PETROL PUMP EXIT, UPPER EAST COAST ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 8824 1

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 X	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00 500 1250	Byper : 550
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 3,000.00 \$	Spoiler : 300 Arch Trim : 200x2 = 400
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 5,272.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 8824 J

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Delud</i>	1	\$ 1,536.00	✓	
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 357.00	+	
3	FRONT BUMPER SECURING STRIP - RH ?	1	\$ 45.00	?	
4	FRONT BUMPER CLOSING ELEMENT - RH ?	1	\$ 133.00	?	
5	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 170.00	+	
6	FRONT BUMPER SPOILER <i>Reg</i>	1	\$ 900.00	+	
7	FRONT BUMPER UNDERRUN BAR <i>at</i>	1	\$ 614.00	-	
8	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 260.00	+	
9	RADIATOR GRILLE <i>at</i>	1	\$ 4,155.00	✓	
10	"QUATTRO" INSCRIPTION <i>new</i>	1	\$ 118.00	✓	
11	RADIATOR GRILLE STRIKER PLATE <i>new</i>	1	\$ 288.00	+	
12	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 691.00	✓	
13	FRONT BUMPER OUTER GRILLE BAFFLE - RH	1	\$ 109.00	✓	<i>} Missing</i>
14	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	1	\$ 46.00	+	
15	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	1	\$ 210.00	✓	
16	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$ 1,104.00	+	
17	FRONT BUMPER TOP COVER	1	\$ 152.00	+	
18	CAUTION SIGN STICKER	1	\$ 17.00	+	
19	AIR CONDITIONER STICKER	1	\$ 24.00	+	
20	HORN HIGH TONE - RH	1	\$ 220.00	+	
SUB TOTAL SPARE PARTS		:	\$ 11,149.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 8824 J

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT PARKING AID SENSOR - OUTER ?	1	\$ 272.00	?	
22	FRONT PARKING AID SEAL RING }	4	\$ 11.00	x	
23	FRONT BUMPER WIRING SET	1	\$ 457.00	x	
24	HEADLIGHT MOUNTING - RH } <i>Not u</i>	1	\$ 140.00	x	
25	HEADLIGHT - RH	1	\$ 9,226.00	x	
26	LIFT CYLINDER - RH } ?	1	\$ 162.00	?	
27	LIFT CYLINDER HOSE } <i>Not u</i>	1	\$ 150.00	x	
28	OUTSIDE TEMPERATURE SENSOR BRACKET <i>Not u</i>	1	\$ 20.00	x	
29	RADIATOR AIR GUIDE - RH }	1	\$ 70.00	x	
30	RADIATOR AIR GUIDE - CENTER	1	\$ 61.00	x	
31	RADIATOR AIR GUIDE - UPPER	1	\$ 61.00	x	
32	FRONT WHEEL HOUSING LINER - RH } <i>Not u</i>	1	\$ 326.00	x	
33	FRONT WHEEL SPOILER	1	\$ 182.00	x	
34	FRONT WHEEL COVER - LH / RH <i>Not u</i>	2	\$ 1,504.00	✓	
35	FRONT NUMBER PLATE <i>Not u</i>	S/N	\$ 60.00	✓	
36	SUNDRIES ?		\$ 400.00	?	
TOTAL SPARE PARTS		:	\$ 24,251.00		
TOTAL LABOUR CHARGES		:	\$ 5,272.00		
GRAND TOTAL		:	\$ 29,523.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *28/02/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not authorised, 03 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: