

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/HLA23002195/SNY3Q2**Date:** 03/04/2023**REFERENCE**

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP318936
<b>Claimant Vehicle No :</b>	SHD6821S	<b>Insured Vehicle No :</b>	SLR8346M
Date of Loss:	16/02/2023	Nature of Claim:	TP
		Claim No:	MPC04026

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHD6821S</b>		
Make & Model:	MERCEDES-BENZ 220E, 2.2 (A)	Engine No:	65192433225837
Reg. Date:	08/04/2016 (Man. Year: 2015)	Chassis No:	WDD2120012B309369
Colour:	White	Odometer:	882326 km
Engine Capacity:	2143 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/55 R16	Rear Tyre Size:	225/55 R16
Front Left Side:	Giti 5 mm	Rear Left Side:	Giti 5 mm
Front Right Side:	Giti 5 mm	Rear Right Side:	Giti 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,308.00	0.00	1,308.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	680.00	200.00	22.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,188.00</b>	<b>680.00</b>	<b>1,508.00</b>	<b>68.92</b>
<b>+ GST 8.00/8.00% (S\$)</b>	175.04	54.40	120.64	68.92
<b>Nett Amount (S\$)</b>	<b>2,363.04</b>	<b>734.40</b>	<b>1,628.64</b>	<b>68.92</b>

**INSPECTION**

Date of Assignment:	01/03/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	01/03/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

**Adjuster:** S Mohamed Irfan Bin Mohamed Iqbal**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2023)
Parts:	143	MERCEDES-BENZ 220E 2.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD6821S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Repair	1,510.00 FL	*- FL
2	1		*REAR BUMPER BRACKET RH	Not Necessary	125.00 FL	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					1,635.00	0.00
- List Item Discount on L Items 20.00/20.00% (S\$)					327.00	0.00
Total Parts (S\$)					1,308.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	450.00	400.00
2	SPRAY PAINTING CHARGE	New	350.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>880.00</b>	<b>680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >