

# CARSMITH PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-20 Singapore 417807

Tel: 9091 0000/ Email: info@carsmith.biz

not Authorized  
Ler  
1/3/23  
2/58 5200/  
5 days

VEHICLE NO: SJD2103J

MAKE & MODEL: MITSUBISHI LANCER

DOA: 27.02.2023

CLAIM TYPE: TP CLAIM

## ESTIMATION QUOTE

nett item

| PARTS                             | QTY       | PRICE (\$)  | REMARKS    |
|-----------------------------------|-----------|-------------|------------|
| REAR BUMPER 731                   | 1         | \$ 868.00   | Dis ✓      |
| REAR BUMPER LOWER LIP             | 1         | \$ 480.00   | Det/turn ✓ |
| REAR BUMPER RETAINER LH           | 1         | \$ 81.00    | 17 X       |
| REAR BUMPER RETAINER RH           | 1         | \$ 81.00    | but ✓      |
| BOOTLID                           | 1         | \$ 782.00   | 20/24c ✓   |
| BOOTLID LOGO 52                   | 1         | \$ 63.00    | 2er ✓      |
| BOOTLID LOCK 197                  | 1         | \$ 258.00   | 2er/2er ✓  |
| BOOTLID LOCK STRIKER              | 1         | \$ 50.00    | 17 X       |
| BOOTLID HINGE                     | 2         | \$ 256.00   | 17 X       |
| BOOTLID WEATHERSTRIP              | 1         | \$ 260.00   | 2er ✓      |
| BOOTLID licence plate garnish 248 | 1         | \$ 378.00   | CRG ✓      |
| TAILLAMP LH 468                   | 1         | \$ 574.00   | scr/ene ✓  |
| TAILLAMP RH 468                   | 1         | \$ 574.00   | CRG ✓      |
| REAR END PANEL 442                | 1         | \$ 689.00   | badly ✓    |
| REAR END PANEL TOP GARNISH 166    | 1         | \$ 275.00   | 2er ✓      |
| SPARE TYRE PANEL                  | 1         | \$ 589.00   | 2er X      |
| SPARE TYRE PANEL TOP BOARD 268    | 1         | \$ 348.00   | 2er ✓      |
| REAR FENDER RH                    | 1         | \$ 1,213.00 | 2 X        |
| REAR FENDER INNER SHIELD RH       | 1         | \$ 225.00   | 17 X       |
| REAR FENDER INNER TRIM RH 316     | 1         | \$ 478.00   | 2er ✓      |
| REAR FENDER INNER TRIM LH 316     | 1         | \$ 478.00   | 17 X       |
| EXHAUST MOUNTING                  | 1         | \$ 80.00    | 17 X       |
| EXHAUST MOUNTING SILENCER         | 1         | \$ 790.30   | 2 X        |
|                                   |           | \$ 9,855.30 |            |
|                                   | LESS 10%  | \$ 985.53   |            |
|                                   | SUB TOTAL | \$ 8,869.77 |            |

| SPECIAL NETT ITEMS               | QTY       | PRICE (\$) | REMARKS   |
|----------------------------------|-----------|------------|-----------|
| REAR BUMPER CLIP                 | 1 SET     | \$ 50.00   | 2er 30    |
| REAR FENDER INNER SHIELD CLIP LH | 1 SET     | \$ 50.00   | 17 X      |
| REAR FENDER INNER SHIELD CLIP RH | 1 SET     | \$ 50.00   | 17 X      |
| REAR FENDER INNER TRIM CLIP LH   | 1 SET     | \$ 50.00   | 17 X      |
| REAR FENDER INNER TRIM CLIP RH   | 1 SET     | \$ 50.00   | 17 X      |
| REAR NUMBER PLATE                | 1         | \$ 90.00   | 17 X      |
| BOOTLID INSULATOR CLIP           | 1 SET     | \$ 50.00   | 17 X      |
| REVERSE SENSOR                   | 1 SET     | \$ 480.00  | shold 200 |
| JOINT SEALANT end panel          | 1         | \$ 100.00  | 2er 50    |
|                                  | SUB TOTAL | \$ 970.00  |           |

| LABOUR                                | QTY | PRICE (\$) | REMARKS |
|---------------------------------------|-----|------------|---------|
| CHECK REAR WIRING AND LIGHTING SYSTEM | 1   | \$ 100.00  | 20      |

|                                                        |   |             |     |
|--------------------------------------------------------|---|-------------|-----|
| REMOVE AND RENEW REAR SENSOR                           | 1 | \$ 120.00   | 50  |
| REMOVE AND REFIT REAR LINING, TRIM AND GARNISH         | 1 | \$ 150.00   | 80  |
| PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS | 1 | \$ 1,500.00 | 800 |
| SPRAY PAINTING ON AFFECTED AREAS                       | 1 | \$ 1,500.00 | 900 |
| APPLY ANTI RUST ON AFFECTED AREAS                      | 1 | \$ 100.00   | 60  |

SUB TOTAL \$ 3,470.00

GRAND TOTAL \$ 13,309.77

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 4804  
10%  
4377.6  
280  
1910  
6567.6