

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8046Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
2	REAR BUMPER SIDE BRACKET LH / RH @\$55.80	NOT NECESSARY	111.60	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	41.50	-
2	REAR REINFORCEMENT STAY LH / RH @\$138.10	NOT NECESSARY	276.20	-
2	REAR NUMBER PLATE LAMP LH / RH	NOT NECESSARY	85.30	-
1	TOWING COVER	NOT NECESSARY	98.80	-
2	REAR FOG LAMP	CRACKED	201.50	201.50
	LESS 20% DISCOUNT		-428.47	-134.95
			1,713.88	539.80
	NETT ITEMS			
1	REAR REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
	LESS 10% DISCOUNT		-	-18.00
			180.00	162.00
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE W/HOLDER (SN)	CRACKED	55.00	55.00
1	REAR BUMPER ADVERTISEMENT (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LH / RH (SN)	NECESSARY	461.50	461.50
			566.50	566.50
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		600.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	TUFF COATING.	NOT NECESSARY	60.00	-
	CHECK WIRING AND LIGHTING.		60.00	30.00

Report Ref No. NS/INC23002201/Tnp3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE / REFIX REVERSE SENSOR.		60.00	30.00
			1,080.00	660.00
	GRAND TOTAL		3,540.38	1,928.30

RECOMMENDED COST OF LUMP SUM REPAIRS	1,550.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. NS/INC23002201/Tnp3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

BEng(Hons),B.Bus,MBA,PEng,PE,

MInstAEA, MASME, MIRTE

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.