

RECEIVED

REF:

INC

ASSIGNMENT

Form: _____ Date: _____
Estimated loss: _____
ID / TP / VS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
Workshop No: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: _____
DAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Turn Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT
WP
chany

Date / Time	Action / Instruction

Veh No: SH8046Z Yr Regn: 2019 04
Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /
Truck / Trailer or
Make: Hyundai C.D. 1580
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 317854 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: KM HC851 CUK4141553
Gen. Cond: Good / Fair / Poor / Burnt
Steering: in order / Jammed / Leaked / Burnt or
Brake: in order / Jammed / Leaked / Burnt or
Mod: MD / S/Rim / STD A/Rim or
Tyre Size: F: 195/65K15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /
TOYO / YOKO, or
Front
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 27/2/23
Survey held at Comfort 6zy
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof top or
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to? ☐ : Prel. Report
1) ☐ : Final Report
Date/Time, File Return to?
2) _____
Report Format: _____
Lump Sum / L2-R up

Days Of Repair: _____
Resurvey No. of Trip: _____
Survey Fee: _____
Transportation: _____
Add Fee: ☐ : Site Insp (3)
☐ : Interview (3)
☐ : Tech. (3)
B + RS 31

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH 8046Z

26.02.2023

MAKE REG. 02.04.2019

CHIANG/INCOME

MODEL IONIQ G2

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		Ry \$459.40
1	REAR BUMPER SIDE BRACKET LH/RH		\$55.80 x \$111.60
10	REAR BUMPER CLIPS		\$2.20 nei \$22.00
1	REAR BUMPER CENTRE MOULDING		de \$451.25
1	REAR BUMPER REINFORCEMENT		? \$394.80
1	REAR BUMPER REFLECTOR LH		x \$41.50
1	REAR REINFORCEMENT STAY LH/RH		\$138.10 ? \$276.20
2	REAR NUMBER PLATE LAMP LH/RH		? \$85.30
1	TOWING COVER		x \$98.80
2	REAR FOG LAMP		fra \$201.50
	SUB TOTAL		\$2,142.35
	20.00%		\$428.47
	DISCOUNTED TOTAL		\$1,713.88
1	REAR NUMBER PLATE W/HOLDER		cm \$55.00
1	REAR REVERSE SENSOR		nr \$180.00
1	REAR BUMPER ADVERTISEMENT		nei \$50.00
2	REAR FENDER ADVERTISEMENT LH/RH		wh \$461.50
	Labour Charge		
	Panel Beating		350 \$600.00
	Spray Painting Charge		250 \$300.00
	Tuff Coating		x \$60.00
	Check Wiring and Lighting		30 \$60.00
	Remove/refix Reverse sensor		30 \$60.00
	TOTAL LABOUR		\$1,080.00
	ESTIMATE TOTAL		\$3,255.38
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphin 97495749
 W8' 27/2/23 2415
 1/3 Resurvey after repair
 2 days
 Tanphin @ Kianpaw

Date/Time: 27.02.2023 12:41

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5887311

JC NO305546644

STOMER

COMFORT TRANSPORTATION PTE LTD
STOMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

COUNT CARD NO.


REGN NO.: SH 8046Z	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 27.02.2023 09:20
YR OF MANU. 02.04.2019	TARGET DATE
CHASSIS CODE KMHC851CVKU141553	COMPLETION DATE/TIME:

accident Date: 26.02.2023
NATURE: 3P 26.02.2023

S/NO LABOR CODE

JOB DESCRIPTION

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

Vehicle No.: SH 8046Z

Vehicle No.: SH 8046Z

Signature/Date

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard