

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH 8046Z

26.02.2023

MAKE REG. 02.04.2019

MODEL IONIQ G2

CHIANG/INCOME

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		Ry \$459.40
1	REAR BUMPER SIDE BRACKET LH/RH		\$55.80 mX \$111.60
10	REAR BUMPER CLIPS		\$2.20 nei \$22.00
1	REAR BUMPER CENTRE MOULDING		de \$451.25
1	REAR BUMPER REINFORCEMENT		un Z \$394.80
1	REAR BUMPER REFLECTOR LH		un X \$41.50
1	REAR REINFORCEMENT STAY LH/RH		\$138.10 Z \$276.20
2	REAR NUMBER PLATE LAMP LH/RH		Z \$85.30
1	TOWING COVER		X \$98.80
2	REAR FOG LAMP		ga \$201.50
	SUB TOTAL		674.75 \$2,142.35
	20.00%		539.80 \$428.47
	DISCOUNTED TOTAL		\$1,713.88
1	REAR NUMBER PLATE W/HOLDER		10% ch \$55.00
1	REAR REVERSE SENSOR		10% nro \$180.00
1	REAR BUMPER ADVERTISEMENT		nei \$50.00
2	REAR FENDER ADVERTISEMENT LH/RH		un \$461.50
	Labour Charge		728.50
	Panel Beating		350 \$600.00
	Spray Painting Charge		250 \$300.00
	Tuff Coating		660 X \$60.00
	Check Wiring and Lighting		1928.30 30 \$60.00
	Remove/refix Reverse sensor		4581550 30 \$60.00
	TOTAL LABOUR		02 days \$1,080.00
	ESTIMATE TOTAL		\$3,255.38
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanphui 97495749 (wp' 27/1/23 2415)
1/3 Resurvey after repair
2 days
Tanphui @Chiang