## COMFORTDELGRO ENGINEERING PTE LTD

## **REPAIR ESTIMATE\***

**VEHICLE NO** 

SHD4453E

REG. 22.10.2019

26.02.2023

CHIANG/FUND TO COME

MAKE MODEL

**IONIQ G3** 

Qty	Parts Description/ Labour	Туре		Amount
1	REAR BUMPER			RY\$459.40
1	REAR BUMPER SIDE BRACKET LH/RH		\$55.80	ハメ \$111.60
10	REAR BUMPER CLIPS		\$2.20	M- \$22.00
1	REAR BUMPER CENTRE MOULDING			\$451.25
1	REAR BUMPER REINFORCEMENT		V	\$394.80
1	REAR REINFORCEMEN STAY LH/RH		\$138.10	\$276.20
2	REAR NUMBER PLATE LAMP LH/RH		ı	√   √
1	TOWING COVER		٨	^ × \$98.80
2	REAR FOG LAMP		Cra	\$201.50
	SUB TOTAL		674.75	\$2,100.85
	20.00%	Y Y	30.00	\$420.17
	DISCOUNTED TOTAL		539,80.	\$1,680.68
M.V.	REAR BUMPER MAT	1	U	\$50.00
2	REAR FENDER ADVERTISEMENT LH/RH		1	\$100.00
T)	REAR NUMBER PLATE W/HOLDER		(-10%) 49.50	\$55.00
1	REAR REVERSE SENSOR		N	√ \$180.00
	÷			\$361.50
	Labour Charge			
	Panel Beating		3	\$600.00
	Spray Painting Charge		<del>30</del> 660 <sup>2</sup>	\$300.00
	Check Wiring and Lighting			307 \$60.00
İ	Remove/refix Reverse sensor	•	1,349.30	子 <sup>つ</sup> \$60.00
	TOTAL LABOUR		<del>1,24 0</del>	\$1,020.00
			45\$1050	
	ESTIMATE TOTAL		2 days XX	\$3,062.18
			0	
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will			
	be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tanjohn 97495719

WP, 26/2/136 3/5/2

LIS Resny after reprir

Janjohn e behands von
2 dezz

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis