

RECEIVED: 20/1/23

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop no: _____

or _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

WP
Amey

Date / Time Action / Instruction

Veh No: SHD 4463E Yr Regn: 2019 out

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai louis C.D. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: UMHLC851CV64187369

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: UP / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /

TOYO / YOKO, or

Westlake

Front

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 20/2/23

Survey held at Compt Louis

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp

☐ : Interview

☐ : Mark

S + RS \$

Power

Other

By/Time/Date:

amp Sign: _____

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD4453E

26.02.2023

MAKE REG. 22.10.2019

CHIANG/FWD *In come*

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		<i>R✓</i> \$459.40
1	REAR BUMPER SIDE BRACKET LH/RH		\$55.80 <i>X</i> \$111.60
10	REAR BUMPER CLIPS		\$2.20 <i>ne✓</i> \$22.00
1	REAR BUMPER CENTRE MOULDING		<i>de✓</i> \$451.25
1	REAR BUMPER REINFORCEMENT		<i>?</i> \$394.80
1	REAR REINFORCEMENT STAY LH/RH		<i>?</i> \$276.20
2	REAR NUMBER PLATE LAMP LH/RH		\$138.10 <i>X</i> \$85.30
1	TOWING COVER		<i>X</i> \$98.80
2	REAR FOG LAMP		<i>?</i> \$201.50
	SUB TOTAL		\$2,100.85
	20.00%		\$420.17
	DISCOUNTED TOTAL		\$1,680.68
1	REAR BUMPER MAT		<i>X</i> \$50.00
2	REAR FENDER ADVERTISEMENT LH/RH		<i>ne✓</i> \$100.00
1	REAR NUMBER PLATE W/HOLDER		<i>ne✓</i> \$55.00
1	REAR REVERSE SENSOR		\$180.00
			\$361.50
	Labour Charge		
	Panel Beating		<i>350</i> \$600.00
	Spray Painting Charge		<i>250</i> \$300.00
	Check Wiring and Lighting		<i>30?</i> \$60.00
	Remove/refix Reverse sensor		<i>30</i> \$60.00
	TOTAL LABOUR		\$1,020.00
	ESTIMATE TOTAL		\$3,062.18
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495719
wp, 26/2/23 @ 3:50pm
L/S Ready after repair
Tanpin e lkhands.com
2 days

Date/Time: 28.02.2023 09:41

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5887497

JC NO305546721

STOMER

/MS COMFORT TRANSPORTATION PTE LTD

STOMER NO. 7010045

DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

.. (R) 65508755

(O)

(P)

COUNT CARD NO.

REGN NO.:

SHD4463E

MILEAGE

MAKE:

HYUNDAI

FUEL

E..... 1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN

26.02.2023 22:45

YR OF MANU.

25.10.2019

TARGET DATE

CHASSIS CODE

KMHC851CVLU187369

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 26.02.2023

NATURE: 3P 26.02.2023

3/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

1.

2. SHD4463E

CHIANG

3. e No.:

Vehicle No.: SHD4463E

4. of Service Advisor

Signature/Date

Name of Service Advisor

Date

5. returned to Service Reception upon collection

To be kept by Security Guard