

NS/INC23002206/Tqp3

ASSIGNMENT

Form: _____ Date: _____
 Estimated Cost: _____
 ID / TP / VS / TP RES / OD RES / EVA / INV / MV
 Inspection Vehicle No: _____
 Workshop No: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bel. or Market Value: _____
 IDAC Accident Report Consistent? : Yes or No
 GIA / PR Seent Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Turn Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: WP' dny Vehicle: IN / OUT

Veh No: SHD4867Z Yr Regn: 20/6/10
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Prius C.D. 1798
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 740524 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTDKB3F4X03533497
 Gen. Cond: 8 / Fair / Poor / Burnt
 Steering: 8 / Inorder / Jammed / Leaked / Burnt or
 Brakes: 8 / Inorder / Jammed / Leaked / Burnt or
 Mod: 8 / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: u
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /
 TOYO / YOKO, etc Westlake
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. D.O.I. 27/2/23
 Survey held at Comfart Logey
 Des. of Damages: Fri / Rear / O/S / N/S / U/C / Roofing or
Front o/s
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Taufikh finalised LS \$1850, 3 days. (Red \$3930.88, 68%)

Date/Time, File Pass to? ☐ : Prel. Report
 1) 05/05 Typist ☐ : Final Report
 Date/Time, File Return to?
 2) _____
 Repair Form: TP
 Lump Sum / L.S. : LS \$1850

Days Of Repair: 3
 Resurvey No. of Trip: 1
 Survey Fee: _____
 Transportation: _____
 Add Fee: ☐ Site Insp ☐ Interview ☐ Tech. Insp ☐ Others

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD4867Z

DATE 24.02.2023

MAKE REG 07.10.2016

MODEL PRIUS G4

CHIANG/INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			de \$586.18
1	FRT BUMPER TOW COVER			X \$28.38
1	FRT GRILLE EMBLEM			ny \$88.00
1	FRT RUNNING DAYLIGHT RH			X \$920.00
1	HEAD LAMP RH			X \$2,637.60
1	FRONT FENDER SHIELD RH			X \$198.50
1	FRONT FENDER LH			bf \$1,111.93
1	FRONT FENDER EMBLEM			ny \$86.50
1	FRT BUMPER SIDE RETAINER /RH			✓ \$90.75
	SUB TOTAL			\$5,747.84
	LESS 25%			\$1,436.96
	DISCOUNTED TOTAL			\$4,310.88
	Labour Charge			
	Panel Beating			350 \$750.00
	Spray Painting Charge			500 \$600.00
	Check Wiring			X \$60.00
	Reset Front Wheel Alignment			✓ \$60.00
	TOTAL LABOUR			\$1,470.00
	ESTIMATE TOTAL			\$5,780.88
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:

Tanjong 92495749
 'wp' 22/2/23 C Pm
 C/B Rosy after repair
 Tanjong C. Khaw to wn
 - 3 days

Team: ARC Repair TP(CLSO)1	JOB CARD Sales Order: 5887226	JC NO305546612
CUSTOMER	REGN NO: SHD4867Z	MILEAGE
MS COMFORT TRANSPORTATION PTE LTD	MAKE: TOYOTA	FUEL
CUSTOMER NO. 7010045	MODEL	E.....1/2.....F
ADDRESS 383 SIN MING DRIVE	PRIUS HYBRID(G4)25.02.2023 10:15	DATE/TIME IN
Singapore SINGAPORE 575717	YR OF MANU. 07.10.2016	TARGET DATE
(R) 65508755 (O)	CHASSIS CODE	COMPLETION DATE/TIME:
COUNT CARD NO.	JTDKB3FUX03533499	

Accident Date: 24.02.2023	JOB DESCRIPTION	
ATURE: 3P 24.02.2023		
/NO	LABOR CODE	DESCRIPTION
		

WORKED & PASSED OUT BY:	
SERVICE ADVISOR	CUSTOMER'S SIGNATURE
acknowledgement Slip	Exit Pass
No.: SHD4867Z CHIANG	Vehicle No.: SHD4867Z
Signature/Date	Name of Service Advisor
Signature/Date	Date
turned to Service Reception upon collection	To be kept by Security Guard