

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0221/2023/EQ

19-Apr-23

CHANG

1 of 1

SKN 7313 Y

AUDI A1 SB S LINE 1.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO DISMANTLE AND REPLACE LH FRONT FENDER.	\$ 1,400.00	500
Parts			
1	FRONT FENDER - LH Buckled.	\$ 1,156.00	✓
GRAND TOTAL		\$ 2,556.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling.
sls

Add 4 days. (3 days for
Lock carrier,
1 day for fender)

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKN 7313 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	<i>to ?</i>
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00 500	<i>868.</i>
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ (1,400.00)	<i>to ?</i> \$ 480
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	<i>?</i> <i>868.</i>
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT FENDERS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00 500	<i>to ?</i> + \$1,250
TOTAL LABOUR CHARGES		\$ 8,560.00	<i>(Remove lock carrier)</i>

+ additional 4 working days.

868.

(Remove lock carrier)

+ additional 3 working days.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKN 7313 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDER. <i>LHS.</i>	\$ 3,500.00	<i>SSO +550.</i>
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	<i>✓</i>
TOTAL LABOUR CHARGES		: \$ 12,252.00	

Car in 18/4/23 wpr 65254

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ATQ - Adcom

- 3 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 7313 Y

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>rehd</i>	1	\$ 2,515.00	-
2	FRONT BUMPER FIXING PARTS <i>Neu</i>	1	\$ 151.00	+
3	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Neu</i>	2	\$ 670.00	+
4	FRONT BUMPER SPOILER - CENTER <i>?</i>	1	\$ 253.00	+
5	FRONT BUMPER GRILLE - CENTER <i>Neu Neu</i>	1	\$ 231.00	+
6	FRONT BUMPER CLOSING ELEMENT	1	\$ 248.00	+
7	RADIATOR GRILLE <i>crackd</i>	1	\$ 1,090.00	✓
8	RADIATOR GRILLE CLOSING ELEMENT <i>crackd</i>	1	\$ 189.00	✓
9	FRONT BUMPER FOAM FILLER PIECE <i>crackd</i>	1	\$ 139.00	✓
10	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ 813.00	?
11	FRONT BUMPER GUIDE PROFILE - LH / RH <i>Neu</i>	2	\$ 86.00	+
12	FRONT BUMPER GUIDE SECTION <i>LH / RH</i> <i>Damaged</i>	2	\$ 254.00	+
13	FRONT BUMPER TOP COVER <i>?</i>	1	\$ 145.00	✓
14	CAUTION SIGN STICKER <i>Neu</i>	1	\$ 17.00	+
15	AIR CONDITIONER STICKER <i>Neu</i>	1	\$ 24.00	+
16	HORN HIGH TONE - LH <i>Neu</i>	1	\$ 157.00	+
17	HORN LOW TONE - RH <i>Neu</i>	1	\$ 149.00	+
18	HORN BRACKET HIGH TONE - LH <i>Neu</i>	1	\$ 47.00	+
19	HORN RETAINER LOW TONE - RH <i>Neu</i>	1	\$ 35.00	+
20	BONNET <i>Neu Neu</i>	1	\$ 2,857.00	+
SUB TOTAL SPARE PARTS		:	\$ 10,070.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 7313 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	LOCK CARRIER ?	1 S	1,497.00 ?	
42	A/C CONDENSER Dented.	1 S	547.00 ✓	H.S.
43	RADIATOR New	1 S	1,023.00 +	
44	RADIATOR New	1 S	1,023.00 +	
45	RADIATOR AIR GUIDE - LH / RH New	2 S	106.00 +	
46	RADIATOR AIR GUIDE SEALING STRIP - LH / RH	2 S	72.00 X	
47	RADIATOR AIR GUIDE RUBBER BUSH - UPPER	2 S	92.00 X	
48	RADIATOR AIR GUIDE BUSH - LOWER	2 S	22.00 +	
49	READY-MIX COOLANT New	6 S	326.00 +	
50	RADIATOR AIR FUNNELS	1 S	57.00 X	
51	RADIATOR AIR INTAKE HOSE	1 S	45.00 +	
52	FRONT WHEEL HOUSING LINER - LH / RH	2 S	418.00 +	
53	FRONT NUMBER PLATE New	S/N S	60.00 ✓	
54	SUNDRIES ?	S	500.00 ?	
TOTAL SPARE PARTS		:	\$ 31,468.00	
TOTAL LABOUR CHARGES		:	\$ 12,252.00	
GRAND TOTAL		:	\$ 43,720.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.