



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD

Ref: CS/HSB23002213/Kqp3

10 MARINA BOULEVARD

Date: 01/03/2023

#48-01 MARINA BAY FINANCIAL CENTRE TOWER

2SINGAPORE 018983

Code: HSB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3193U	Veh. Inspected	SCZ 8877L
Policy No.		Coverage (\$)	0.00
Claim No.	S3M04JP0	Excess (\$)	0.00
Assign From	LOH CYNTHIA	Assign Date	01/03/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	21/02/2023	Inspection Date	01/03/2023
Survey held at	BCC AUTOMOTIVE PTE LTD BLK 1 SIN MING INDUSTRIAL EST SECTOR C #01-101 SINGAPORE 575636.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--