

(08/11/13) wef  
ASS. REC. BY: *[Signature]*

REF:

CS/CT 23002217/Rvp3

761E

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To inspect Vehicle No: SLN 6499P  
at Workshop n/s CYUG & CARRIAGE PL  
of 209, PANDAN GARDEN  
Insured: XE 7033Z CTI  
Policy No. DMCVSNA00138302201  
Claims No. SNM23D201450/C02/KHONGLH  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 69K  
IDAC Accident Rpt: Consistent? : Yes or No  
GIA / PR Seen: Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLN 6499P Yr Regn: 2017 / MAY  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: KIA CARENS 1.7 DCT DIESEL c.c 1685  
Colour: GREEN A/C: Insured / Std / NI / NA  
Sp. Reading: 104104 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: KNATHU 815VH7178009  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or  
Brake: Inorder / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 225/45R17  
R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or CONTINENTAL

Front Rear  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 15/02/23 D.O.I. 01/06/23  
Survey held at CYUG (PG)

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 37K

28/6/23 Final fig \$2607 confirmed by email (Red 13,474, 83%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 28/6/23-typist

Days Of Repair: 3

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

) \$ + RS, SI

) Photos

) Others

Report Format : Merimen

Lump Sum / I.B.I.: (\$ 2607 )

TOTAL

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	20/02/2023 09:50 (SGT)
Reported by	Driver
Date of Accident	15/02/2023 17:29 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	PIE TOWARDS CHNAGI, ENTRY TO KJE
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN6499P
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TEO NI NI CHERYL
NRIC No	SXXXX761E
Email Address	TNNSW828@GMAIL.COM
Mobile Phone No	(Phone) +65-97435498
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Kia
Model	Carens
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1685

#### INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	1700003432-05

#### DRIVER

Name of Driver	WEE KOK CHENG SIMON
NRIC No	SXXXX751G
Date Of Birth	04/07/1970
Occupation	Indoor



Date Of Driving Pass	22/02/1996
Driving experience	27 YEARS
Gender	Male
Mobile Number	(Phone) +65-91396399
Alt. Phone Number	-
Email Address	WEE_SIMON@HOTMAIL.COM
Address	73 CHOA CHU KANG LOOP #01-12
Address complement	-
Postcode	689674
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### PASSENGER 1

Name	WEE KOK CHENG SIMON
Gender	Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE7033Z
Vehicle Manufacturer	Mercedes
Vehicle Model	-
Vehicle Variant	-



Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	WANG FENG
Contact Number	(Phone) +65-87499813
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Teo Ni Ni Cheryl	Cust No/Name /Teo Ni Ni Cheryl
73 Choa Chu Kang Loop	Reg No/Reg Date SLN6499P / 12/05/201
#01-12 Northvale	Date In/Mileage / 0
Singapore 689674	Chassis No KNAHU815VH7178009
Contact No Mobile: 97435498	Engine No D4FDHH102929
	Make/Model KIA/CARENS 1.7 A D SX FL DY6
	Colour/Trim 3D BRIGHT SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	21/02/2023/ 19:59	TLV	1015/ Vikneswaran Naidu A	64556		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000	/	X					640 3840.00
RENEW RR BUMPER & TAILGATE							
REPAIR RR END PNL							
E PNT98000	/	X	X				550 2200.00
RESPRAY RR BUMPER , TAILGATE & RR END PNL							
E PNT88000							280.00
REMOVE & REFIT TAILGATE COMPONENT							
E PNT88000							280.00
REMOVE & REFIT RR FLR BOARD , TRIM & CARPET							
A 54900099							100.00
CHECK WIRING ELECTRICAL SYSTEM							
A 10028901							280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
E PNT88000							280.00
REMOVE & REFIT RR WS GLASS							
M SUNDRY							80.00
SUPPLY WS SEALANT							
M SUNDRY							80.00
SUPPLY RR NUMBER PLATE WITH CASING							
E PNT88000							100 120.00
REMOVE & REFIT REVERSE SENSOR							
M SUNDRY							180.00
APPLY ANTI CORROSION ON AFFECTED AREAS							
M SUNDRY							80.00
SUPPLY BODY PNL SEALANT							
M SUNDRY							50.00
SUPPLY C&C BADGE							
M SUNDRY							100.00
Sundries							
M COVER-RR BUMPER,UPR					1.00	691.00 00.00	691.00
M COVER-RR BUMPER LWR					1.00	226.00 00.00	226.00
M WIRING HARNESS-R.P.A.S					1.00	251.00 00.00	251.00
M BEAM-RR BUMPER					1.00	367.00 00.00	367.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Teo Ni Ni Cheryl 73 Choa Chu Kang Loop #01-12 Northvale Singapore 689674  Contact No Mobile: 97435498	Cust No/Name /Teo Ni Ni Cheryl Reg No/Reg Date SLN6499P / 12/05/201 Date In/Mileage / 0 Chassis No KNAHU815VH7178009 Engine No D4FDHH102929 Make/Model KIA/CARENS 1.7 A D SX FL DY6 Colour/Trim 3D BRIGHT SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	21/02/2023/ 19:59	TLV	1015/ Vikneswaran Naidu A	64556
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M STAY-RR BUMPER LH <del>X</del> <sup>an</sup>		1.00	159.00	00.00	159.00
M STAY-RR BUMPER RH <del>X</del> <sup>an</sup>		1.00	159.00	00.00	159.00
M BRACKET-RR BUMPER RAIL,UPR <del>X</del> <sup>an</sup>		1.00	5.00	00.00	5.00
M BRACKET-RR BUMPER LWR,CTR <del>X</del> <sup>an</sup>		1.00	5.00	00.00	5.00
M ANTENNA ASSY-SMARTKEY <del>X</del> <sup>an</sup>		1.00	79.00	00.00	79.00
M BRACKET ASSY-RR BUMPER SIDE,LH <del>X</del> <sup>an</sup>		1.00	25.00	00.00	25.00
M BRACKET ASSY-RR BUMPER SIDE,RH <del>X</del> <sup>an</sup>		1.00	25.00	00.00	25.00
M LAMP ASSY-REAR FOG,LH <del>X</del> <sup>an</sup>		1.00	126.00	00.00	126.00
M LAMP ASSY-REAR FOG,RH <del>X</del> <sup>an</sup>		1.00	126.00	00.00	126.00
M ULTRASONIC SENSOR ASSY-P.A.S <del>X</del> <sup>an</sup>		4.00	162.00	00.00	648.00
M HOLDER-BACK WARING SYSTEM OTR <del>X</del> <sup>an</sup>		2.00	4.00	00.00	8.00
M HOLDER-BACK WARING SYSTEM INR <del>X</del> <sup>an</sup>		2.00	4.00	00.00	8.00
M PANEL ASSY-TAIL GATE <del>X</del> <sup>an</sup>		1.00	1218.00	00.00	1218.00
M EMBLEM-CARENS <del>X</del> <sup>an</sup>		1.00	36.00	00.00	36.00
M EMBLEM-CRDI <del>X</del> <sup>an</sup>		1.00	29.00	00.00	29.00
M GARNISH-TAIL GATE,UPR <del>X</del> <sup>an</sup>		1.00	135.00	00.00	135.00
M MOULDING-CR PIECE <del>X</del> <sup>an</sup>		1.00	104.00	00.00	104.00
M ORNAMENT-KIA <del>X</del> <sup>an</sup>		1.00	76.00	00.00	76.00
M LAMP ASSY-REAR COMB INSIDE,LH <del>X</del> <sup>an</sup>		1.00	773.00	00.00	773.00
M LAMP ASSY-REAR COMB INSIDE,RH <del>X</del> <sup>an</sup>		1.00	773.00	00.00	773.00
M LAMP ASSY-REAR COMBINATION,LH <del>X</del> <sup>an</sup>		1.00	770.00	00.00	770.00
M LAMP ASSY-REAR COMBINATION,RH <del>X</del> <sup>an</sup>		1.00	770.00	00.00	770.00
M GLASS ASSY-TAIL GATE <del>X</del> <sup>an</sup>		1.00	539.00	00.00	539.00

SURVEYOR NAME: Rahul - H990010068  
 SURVEYOR SIGNATURE: [Signature]  
 DATE: 01/06/23 @ 1510  
 REMARKS: 3 days  
Per 54 paint

Confirm &amp; accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Net 16081.00  
 Sign: 16081.00  
 Date: 1286.48  
 Total Payable 17,367.48

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.