



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Teo Ni Ni Cheryl 73 Choa Chu Kang Loop #01-12 Northvale Singapore 689674 Contact No Mobile: 97435498	Cust No/Name	/Teo Ni Ni Cheryl
	Reg No/Reg Date	SLN6499P / 12/05/201
	Date In/Mileage	/ 0
	Chassis No	KNAHU815VH7178009
	Engine No	D4FDHH102929
	Make/Model	KIA/CARENS 1.7 A D SX FL DY6
	Colour/Trim	3D BRIGHT SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	21/02/2023/ 19:59	TLV	1015/ Vikneswaran Naidu A	64556		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000	/	X					646 3840.00
RENEW RR BUMPER & TAILGATE							
REPAIR RR END PNL							
E PNT98000	/	X					550 2200.00
RESPRAY RR BUMPER , TAILGATE & RR END PNL							
E PNT88000							X 280.00
REMOVE & REFIT TAILGATE COMPONENT							
E PNT88000							X 280.00
REMOVE & REFIT RR FLR BOARD , TRIM & CARPET							
A 54900099							100.00
CHECK WIRING ELECTRICAL SYSTEM							
A 10028901							280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
E PNT88000							X 280.00
REMOVE & REFIT RR WS GLASS							
M SUNDRY							X 80.00
SUPPLY WS SEALANT							
M SUNDRY							X 80.00
SUPPLY RR NUMBER PLATE WITH CASING							
E PNT88000							100 120.00
REMOVE & REFIT REVERSE SENSOR							
M SUNDRY							X 180.00
APPLY ANTI CORROSION ON AFFECTED AREAS							
M SUNDRY							X 80.00
SUPPLY BODY PNL SEALANT							
M SUNDRY							X 50.00
SUPPLY C&C BADGE							
M SUNDRY							20 100.00
Sundries							
M COVER-RR BUMPER,UPR					1.00	691.00 00.00	691.00
M COVER-RR BUMPER LWR					1.00	226.00 00.00	226.00
M WIRING HARNESS-R.P.A.S					1.00	251.00 00.00	251.00
M BEAM-RR BUMPER					1.00	367.00 00.00	367.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Teo Ni Ni Cheryl 73 Choa Chu Kang Loop #01-12 Northvale Singapore 689674 Contact No Mobile: 97435498	Cust No/Name /Teo Ni Ni Cheryl Reg No/Reg Date SLN6499P / 12/05/201 Date In/Mileage / 0 Chassis No KNAHU815VH7178009 Engine No D4FDHH102929 Make/Model KIA/CARENS 1.7 A D SX FL DY6 Colour/Trim 3D BRIGHT SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	21/02/2023/ 19:59	TLV	1015/ Vikneswaran Naidu A	64556
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M STAY-RR BUMPER LH		1.00	159.00	00.00	159.00
M STAY-RR BUMPER RH		1.00	159.00	00.00	159.00
M BRACKET-RR BUMPER RAIL,UPR?		1.00	5.00	00.00	5.00
M BRACKET-RR BUMPER LWR,CTR?		1.00	5.00	00.00	5.00
M ANTENNA ASSY-SMARTKEY?		1.00	79.00	00.00	79.00
M BRACKET ASSY-RR BUMPER SIDE,LH X		1.00	25.00	00.00	25.00
M BRACKET ASSY-RR BUMPER SIDE,RH X		1.00	25.00	00.00	25.00
M LAMP ASSY-REAR FOG,LH X		1.00	126.00	00.00	126.00
M LAMP ASSY-REAR FOG,RH X		1.00	126.00	00.00	126.00
M ULTRASONIC SENSOR ASSY-P.A.S?		4.00	162.00	00.00	648.00
M HOLDER-BACK WARING SYSTEM OTR X		2.00	4.00	00.00	8.00
M HOLDER-BACK WARING SYSTEM INR X		2.00	4.00	00.00	8.00
M PANEL ASSY-TAIL GATE X		1.00	1218.00	00.00	1218.00
M EMBLEM-CARENS X		1.00	36.00	00.00	36.00
M EMBLEM-CRDI X		1.00	29.00	00.00	29.00
M GARNISH-TAIL GATE,UPR X		1.00	135.00	00.00	135.00
M MOULDING-CR PIECE X		1.00	104.00	00.00	104.00
M ORNAMENT-KIA X		1.00	76.00	00.00	76.00
M LAMP ASSY-REAR COMB INSIDE,LH X		1.00	773.00	00.00	773.00
M LAMP ASSY-REAR COMB INSIDE,RH X		1.00	773.00	00.00	773.00
M LAMP ASSY-REAR COMBINATION,LH X		1.00	770.00	00.00	770.00
M LAMP ASSY-REAR COMBINATION,RH X		1.00	770.00	00.00	770.00
M GLASS ASSY-TAIL GATE X		1.00	539.00	00.00	539.00

SURVEYOR NAME: Rahul - H990010068SURVEYOR SIGNATURE: [Signature]DATE: 01/06/23 @ 1510REMARKS: 3 daysRepair 54 paint

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer 16,081.00
Signature 1286.48
Date:

8% GST on 16,081.00 1286.48

Total Payable 17,367.48

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	761E
Vehicle No.:	SLN6499P
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jun 2023
Vehicle Make:	KIA
Vehicle Model:	CARENS 1.7 DCT DIESEL 5DR FWD
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	D4FDHH102929
Chassis No.:	KNAHU815VH7178009
Maximum Power Output:	104.0 kW (139 bhp)
Open Market Value:	\$22,817.00
Original Registration Date:	12 May 2017
First Registration Date:	12 May 2017
Transfer Count:	0
Actual ARF Paid:	\$18,944.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 May 2027
PARF Rebate Amount:	\$12,313.00
COE Expiry Date:	11 May 2027
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$48,556.00
COE Rebate Amount:	\$18,972.00
Total Rebate Amount:	\$31,285.00

The information contained herein is correct as at 04 Jun 2023


OK

Kia Carens Diesel 1.7A

\$68,800 Instalment \$1,167/mth









 Apply for 2.28% loan

 Shortlist

 Get Warranty



Overview Financial Photo Research

Depreciation	 \$14,730 / year
Reg. Date	27-Apr-2017 (3yrs 10mths 22days COE left)
Manufactured	 2016
Mileage	97,200 km (15.9k / year)
Transmission	Auto
Engine Cap	1,685 cc
Road Tax	 \$1,318 / year
Power	104.0 kW (139 bhp) View specs of the Kia Carens Diesel (2016-2018)
Curb Weight	 1,525 kg
Fuel Type	Diesel (Euro 5 Engine and Above)
COE	 \$48,556
OMV	 \$25,567
ARF	 \$22,794
Dereg Value	 \$33,601 as of today