

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTChina Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909**Our File No:** CS/CTI23002219/TWP3E2**Date:** 07/03/2023**REFERENCE**

Insured/Claimant: KO TECK CHUAN (GAO DECHUAN) Policy No: DMHCSNW00014152200

Date of Loss: 24/02/2023

Nature of Claim: OD

Claim No: SNM23D201519/C01/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNA5424G**
 Make & Model: BMW 216D, 1.5 D ACTIVE TOURER D/AB LED (A) Engine No: 34839866B37C15A
 Reg. Date: 28/02/2017 (Man. Year: 2017) Chassis No: WBA2B320X0V925743
 Colour: Blue Odometer: 0 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: S\$72,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	1,250.00	1,250.00	0.00	0.00
Nett Amount (S\$)	-1,250.00	-1,250.00	0.00	0.00

INSPECTION

Date of Assignment: 01/03/2023

Date Inspected: 01/03/2023 Inspected At:

6 Marsiling Lane S739145
Repairer: Century Motors Pte Ltd (HQ)

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

TOTAL LOSS ASPECT

Market Value :	\$72,000.00
OMV :	\$27,803.00
PARF Rebate (1) :	\$13,601.00
Quota Premium Paid :	\$48,401.00
COE Rebate (2) :	\$19,331.00
Total Rebate (1) + (2) = :	\$32,932.00

The total amount incurred will be Market Value \$72,000.00 minus Total Rebate \$32,932.00 = \$39,068.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Mar 2023)

Parts: M1-MPV BMW 216D 1.5 D ACTIVE TOURER D/AB LED (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNA5424G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >