

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 02 Mar 2023

Preliminary Advice

Vehicle No	: SMN184A	Accident Date	: 28/02/2023
Make	: TOYOTA SIENTA HYBRID	Policy No.	: SPCM1000000487
Assignment Date	: 01/03/2023	Excess	: S\$2,000.00
Date of Inspection	: 02/03/2023	Est. Duration of Repair	: 5 DAYS
Inspection At	: CHENG HOE MOTOR PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,478.70
Revised Amount	:S\$	3,575.70
Check Items (Estimated)	:S\$	1,683.00
Total	:S\$	5,258.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	93,000.00
COE / PARF Rebate	:S\$	32,119.00
Salvage Value	:S\$	
Margin for Repair	:S\$	60,881.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Part by Part repair. According to the repairer, there are no second-hand parts available. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.