

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 23 May 2023

## **Preliminary Advice**

Vehicle No	: SMN184A	Accident Date	: 28/02/2023
Make	: TOYOTA SIENTA HYBRID	Policy No.	: SPCM1000000487
Assignment Date	: 01/03/2023	Excess	: S\$2,000.00
Date of Inspection	: 02/03/2023	Est. Duration of Repair	: 5
Inspection At	: CHENG HOE MOTOR PLE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,897.70 (Est \$5,478.70 + Supp \$1,419.00)
Revised Amount	:S\$	6,061.70 (Inclu. Supp \$1,419.00)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,061.70
Lump Sum Repair	:S\$	4,250.00

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	93,000.00
COE / PARF Rebate	:S\$	32,119.00
Salvage Value	:S\$	
Margin for Repair	:S\$	60,881.00

### **Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Please approve on supplementary item and cost of repair. The repairer change to Lump Sum repair.
- Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour costs.