



> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

#### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 063G

#### Vehicle Details

Vehicle No.: SMZ4929D  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 21 Feb 2023  
Vehicle Make: MERCEDES BENZ  
Vehicle Model: CLA180 COUPE URBAN (R18 LED)  
Primary Colour: Blue  
Manufacturing Year: 2018  
Engine No.: 27091031680495  
Chassis No.: WDD1173422N687871  
Maximum Power Output: 90.0 kW (120 bhp)  
Open Market Value: \$29,059.00  
Original Registration Date: 02 Aug 2018  
First Registration Date: 02 Aug 2018  
Transfer Count: 1  
Actual ARF Paid: \$32,683.00 *16341*

#### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 01 Aug 2028  
PARF Rebate Amount: \$24,512.00

#### Intended COE Rebate Details

COE Expiry Date: 01 Aug 2028  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$25,000.00  
COE Rebate Amount: \$13,615.00  
**Total Rebate Amount: \$38,127.00**

The information contained herein is correct as at 21 Feb 2023

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	06/02/2023 18:56 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	02/02/2023 03:00 (SGT)
Exact Location of Accident	Penang Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMZ4929D
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Ong Cai Yin
NRIC No	S9628063G
Email Address	sereneong007@gmail.com
Mobile Phone No	(Phone) +65-94886349
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	Cla180
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1600

#### INSURANCE COMPANY

Name of Insurance Company	Etiqa Insurance Pte Ltd
Policy Number / Cover Note Number	MA023154

#### DRIVER

Name of Driver	Ong Cai Yin
NRIC No	S9628063G
Date Of Birth	23/07/1996
Occupation	Outdoor

Date Of Driving Pass	23/12/2016
Driving experience	6 YEARS AND 2 MONTHS
Gender	Female
Mobile Number	(Phone) +65-94886349
Alt. Phone Number	-
Email Address	sereneong007@gmail.com
Address	Blk 247 Jurong East St 24 #07-04
Address complement	-
Postcode	600247
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	4
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	Goh Kai Lin Joreen
Gender	Female

PASSENGER 2

Name	Wendy Teng Wan Lin
Gender	Female

PASSENGER 3

Name	Jeremy lam jinchen
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

refer attached report.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
---	-----

Was there any video captured by Car Camera? No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	Ting Shang Ping
Contact Number	(Phone) +65-98296733
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### INJURED PERSONS DETAILS

##### INJURED 1

Name of injured person	Goh Kai Lin Joreen
Gender	Female
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SMZ4929D
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No

##### INJURED 2

Name of injured person	Wendy Teng Wan Lin
Gender	Female
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SMZ4929D
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No

##### INJURED 3

Name of injured person	Jeremy lam Jinchen
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SMZ4929D
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No



**Describe Circumstance of the Accident**

On 02/03/23 at 05:00am, I was driving my vehicle A (SM249278) along Pnang Road when I was driving straight suddenly I feel a huge impact from the side of my vehicle. After I come down of my vehicle I notice I was hit by vehicle B. Ting Sheng Ping No: 9829 5733 (Car Plate unknown), as he is making a right turn and changing into my lane as a result my driver side was damaged, car not movable, towing service is required.

**Declaration**

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Officer / Personnel  
(Name as in NRIC/ID card)

## Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875  
Tel: 93290237 Email: claims\_rar@bifrostauto.com

SJE : \_\_\_\_\_  
Date of Survey : \_\_\_\_\_  
Date of ReSurvey: \_\_\_\_\_  
Contacts : \_\_\_\_\_

Vehicle Nos : SMZ 4929D  
Made : Mercedes Benz  
Model : CLA 180 Coupe Urban  
Chassis No : \_\_\_\_\_

### \* AGREED Cost Of Repair and Repair Day/s with SJE \*

Amount: \_\_\_\_\_

Working Day: \_\_\_\_\_

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Bumper <i>scr R</i>	1	\$ 1,326.00	\$ 1,329.00
2	Rear Bumper Side Retainer RH <i>X</i>	1	\$ 37.00	\$ 37.00
3	Rear Bumper Side Retainer LH <i>X</i>	1	\$ 37.00	\$ 37.00
4	Rear Bumper Lower <i>X</i>	1	\$ 458.00	\$ 458.00
5	Rear Bumper Chrome Trim Strip <i>X</i>	1	\$ 150.00	\$ 150.00
6	Rear Bumper Reverse Sensor <i>X</i>	6	\$ 182.48	\$ 1,094.88
7	Rear Bumper Reverse Sensor O Ring <i>X</i>	6	\$ 6.35	\$ 38.10
8	Rear Bumper Reverse Sensor Holder Bracket <i>X</i>	6	\$ 40.00	\$ 240.00
9	Rear Bumper Reverse Sensor Wire Harness <i>X</i>	1	\$ 348.87	\$ 348.87
10	Rear Bumper Centre Basic Carrier <i>X</i>	1	\$ 98.00	\$ 98.00
11	Rear Bumper Reinforcement <i>X</i>	1	\$ 465.00	\$ 465.00
12	Rear Taillamp Assembly RH <i>X</i>	1	\$ 853.00	\$ 853.00
13	Rear Taillamp Assembly LH <i>X</i>	1	\$ 853.00	\$ 853.00
14	Rear Fender RH <i>Deny</i>	1	\$ 3,030.00	\$ 3,030.00
15	Rear Fender Inner Cowling RH <i>X</i>	1	\$ 165.00	\$ 165.00
16	Rear Fender Inner Trim RH <i>X</i>	1	\$ 309.00	\$ 309.00
17	Rear Windscreen Glass <i>X</i>	1	\$ 1,087.68	\$ 1,087.68
18	Rear Windscreen Glass Trim Strip <i>X</i>	1	\$ 154.00	\$ 154.00
19	Rear Door RH <i>BUC</i>	1	\$ 2,005.00	\$ 2,005.00
20	Rear Door Outer Handle RH <i>scr X</i>	1	\$ 153.00	\$ 153.00
21	Rear Door Outer Handle Cover RH <i>scr</i>	1	\$ 87.00	\$ 87.00
22	Rear Door Outer Handle Bracket RH <i>X</i>	1	\$ 180.00	\$ 180.00
23	Rear Door Inner Trim Board RH <i>X</i>	1	\$ 1,440.00	\$ 1,440.00
24	Rear Door Lock RH <i>X</i>	1	\$ 356.00	\$ 356.00
25	Rear Door Weatherstrip RH <i>X</i>	1	\$ 314.00	\$ 314.00
26	Rear Door Glass RH <i>X</i>	1	\$ 871.00	\$ 871.00
27	Rear Door Glass Run Channel with Quarter Glass RH <i>X</i>	1	\$ 734.00	\$ 734.00
28	Rear Door 1/4 Window Fixed RH <i>X</i>	1	\$ 255.00	\$ 255.00
29	Rear Door Power Window Regulator RH <i>X</i>	1	\$ 684.00	\$ 684.00
30	Rear Door Power Window Motor RH <i>X</i>	1	\$ 666.00	\$ 666.00
31	Rear Door Outer Chrome Moulding RH <i>X</i>	1	\$ 149.00	\$ 149.00
32	Rear Door Frame Sticker RH <i>X</i>	1	\$ 105.00	\$ 105.00

33	Rear Door Hinge Top RH	X	1	\$	126.00	\$	126.00
34	Rear Door Hinge Bottom RH	X	1	\$	144.00	\$	144.00
35	Rocker Panel Garnish RH	X	1	\$	440.00	\$	440.00
36	Front Door RH	Buc /	1	\$	2,005.00	\$	2,005.00
37	Front Door Outer Handle RH	?	1	\$	153.00	\$	153.00
38	Front Door Outer Handle Cover RH	Scr /	1	\$	81.00	\$	81.00
39	Front Door Outer Handle Bracket RH	?	1	\$	180.00	\$	180.00
40	Front Door Insulator Pad RH	X	1	\$	231.00	\$	231.00
41	Front Door Weatherstrip RH	X	1	\$	342.00	\$	342.00
42	Front Door Hinge Top RH	X	1	\$	126.00	\$	126.00
43	Front Door Hinge Bottom RH	X	1	\$	144.00	\$	144.00
44	Front Door Outer Chrome Moulding RH	Paint /	1	\$	167.00	\$	167.00
45	Front Door Lock RH	X	1	\$	324.00	\$	324.00
46	Front Door Glass RH	BT /	1	\$	733.00	\$	733.00
47	Front Door Glass Run Channel RH	?	1	\$	357.00	\$	357.00
48	Front Door Inner Trim Board RH	?	1	\$	1,440.00	\$	1,440.00
49	Front Door Power Window Regulator RH	?	1	\$	594.00	\$	594.00
50	Front Door Power Window Motor RH	?	1	\$	666.00	\$	666.00
51	Front Door Side Mirror Cover RH	Scr /	1	\$	216.00	\$	216.00
52	Front Door Side Mirror Cover Lower RH	Scr /	1	\$	81.00	\$	81.00
53	Front Door Side Mirror Housing RH	Scr /	1	\$	900.00	\$	900.00
54	Front Door Side Mirror Sealing RH	X	1	\$	36.00	\$	36.00
55	Front Door Side Mirror Motor RH	X	1	\$	198.00	\$	198.00
56	Front Door Side Mirror Glass RH	Br /	1	\$	225.00	\$	225.00
57	Front Door Side Mirror Signal Lamp RH	Scr /	1	\$	218.00	\$	218.00
58	Front Fender RH	Scr R	1	\$	720.00	\$	720.00
59	Front Fender Inner Cowling RH	X	1	\$	225.00	\$	225.00
60	Front Headlamp Assembly RH	X	1	\$	3,020.00	\$	3,020.00
61	Front Headlamp Control Unit RH	X	1	\$	762.00	\$	762.00
62	Front Bumper	Scr / X	1	\$	1,391.33	\$	1,391.33
63	Front Bumper Side Retainer RH	X	1	\$	56.73	\$	56.73
64	Front Wheel Rim RH	Scr R	1	\$	858.38	\$	858.38
65	Front Shock Absorber RH	X	1	\$	773.51	\$	773.51
66	Front Control Arm RH	X	1	\$	864.36	\$	864.36
67	Front Stabilizer Link RH	X	1	\$	81.00	\$	81.00
68	Front Knuckle Arm RH	X	1	\$	1,439.20	\$	1,439.20
69	Front Wheel Bearing RH	X	1	\$	575.41	\$	575.41
70	Front Lower Arm RH	X	1	\$	645.97	\$	645.97
71	Front Strut Rod RH	X	1	\$	649.20	\$	649.20
72	Steering Rack & Pinion	X	1	\$	7,694.86	\$	7,694.86
73	Rear Wheel Rim RH	Scr /	1	\$	858.38	\$	858.38
74	Rear Shock Absorber RH	X	1	\$	432.00	\$	432.00
75	Rear Shock Absorber Spring Shim Upper RH	X	1	\$	36.00	\$	36.00
76	Rear Shock Absorber Spring Shim Lower RH	X	1	\$	36.00	\$	36.00
77	Rear Stabilizer Link RH	X	1	\$	72.00	\$	72.00

78	Rear Knuckle Arm RH	X	1	\$ 1,458.00	\$ 1,458.00
79	Rear Wheel Bearing RH	X	1	\$ 432.00	\$ 432.00
80	Rear Lower Arm RH	X	1	\$ 216.00	\$ 216.00
81	Rear Trailing Arm RH	X	1	\$ 177.00	\$ 177.00
82	Rear Upper Arm RH	X	1	\$ 153.00	\$ 153.00
83	Rear Tie Rod RH	X	1	\$ 72.00	\$ 72.00
				Parts Sub Total :	\$ 52,572.86
				10% Discount	\$ 5,257.29
				<b>PARTS TOTAL :</b>	<b>\$ 47,315.57</b>

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Bumper Clips - Set <i>NCC</i>	1	\$ 50.00	\$ 50.00
2	Rear Fender Inner Cowling RH Clips - Set X	1	\$ 30.00	\$ 30.00
3	Rear Fender Inner Trim RH Clips - Set X	1	\$ 50.00	\$ 50.00
4	Rear Door Inner Trim Board RH Clips - Set X	1	\$ 50.00	\$ 50.00
5	Front Door Inner Trim Board RH Clips - Set <i>NCC</i>	1	\$ 50.00	\$ 50.00
6	Front Fender Inner Cowling RH Clips - Set X	1	\$ 50.00	\$ 50.00
7	Front Bumper Clips - Set <i>NCC</i>	1	\$ 50.00	\$ 50.00
8	Rocker Panel Garnish RH Clips - Set X	1	\$ 50.00	\$ 50.00
9	Rear Fender RH Sealant <i>80</i>	1	\$ 150.00	\$ 150.00
10	Rear Door RH Sealant X	1	\$ 150.00	\$ 150.00
11	Front Door RH Sealant X	1	\$ 150.00	\$ 150.00
12	Front Fender RH Sealant X	1	\$ 150.00	\$ 150.00
13	Rear Windscreen Glass Sealant <i>60</i>	1	\$ 150.00	\$ 150.00
14	Front Tyre RH X	1	\$ 500.00	\$ 500.00
15	Rear Tyre RH X	1	\$ 500.00	\$ 500.00
<b>SPECIAL NETT TOTAL :</b>				<b>\$ 2,130.00</b>

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ <i>1000</i> 2,800.00
2	To Spray Paint Affected Areas	\$ <i>1200</i> 2,000.00
3	Wiring & Bulb Check	\$ <i>30</i> 100.00
4	To Transfer Rear Door Mechanism RH	\$ <i>40</i> 150.00
5	To Transfer Front Door Mechanism RH	\$ <i>40</i> 150.00
6	To Remove & Refix Rear Windscreen Glass	\$ <i>80</i> 150.00
7	To Remove & Refix Front Undercarriage	\$ X 750.00
8	To Remove & Refix Rear Undercarriage	\$ X 750.00
9	To Remove & Refix Front and Rear Tyre and Conduct Wheel Balancing	\$ <i>50</i> 150.00
10	To Conduct Four Wheel Alignment	\$ <i>50</i> 150.00
11	To apply anti rust on affected parts	\$ <i>40</i> 150.00
12	To Conduct Water Leak Test	\$ <i>XNV</i> 100.00
13	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X 480.00
<b>LABOUR TOTAL :</b>		<b>\$ 7,880.00</b>

*6 days*  
*213/23*  
*1pm*  
*L19*  
*from*

PARTS TOTAL :	\$	47,315.57
SPECIAL NETT TOTAL :	\$	2,130.00
LABOUR TOTAL :	\$	7,880.00
<b>GRAND TOTAL :</b>	<b>\$</b>	<b><u>57,325.57</u></b>