

(08/11/13) wef

REF:

ASS. REC. BY: ASUL

415F

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SGX 1911Eat Workshop m/s PREMIUMof 24, Moni SecurInsured: A16

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: TBA

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 248k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGX 1911E Yr Regn: 2020 / OCTType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A7 SP 2.0 TFSI Qu c.c. 1984Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 48513 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAV 222 F22 LWO 13749Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/452R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 26/02/23 D.O.I. 01/03/23Survey held at PREMIUM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT- 158K

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS _____ SI

Photos

Others

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0220/2023/EQ
DATE : 28-Feb-23
WIP : 10063

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/3/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR DHARMARAJ RAMESH
ADDRESS : 70, PHOENIX ROAD
#20-16
SINGAPORE 667973
TELEPHONE : HP +65 92360827
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070154137-01
VEHICLE NO : **SGX 1911 E**
MODEL CODE : AUDI A7 SB 2.0 TFSI S
MODEL YEAR : 30/10/2020
ENGINE NO : DLH 066891
CHASSIS NO : WAUZZZF22LN013749
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Feb-23
PLACE OF ACCIDENT : HILL V2 MALL, HILL VIEW

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGX 1911 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 / 250	
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,600.00 ?	
4	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$ 280.00 /	
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. TO REPAIR LHS FRONT DOOR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,000.00 / 1500	
6	TO RESPRAY FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS UPPER A-PILLAR AND LHS FRONT DOOR.	\$ 5,000.00 / 2200	
TOTAL LABOUR CHARGES		: \$ 13,760.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGX 1911 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	240
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 14,472.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGX 1911 E

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>form / ?</i>	1	\$ 3,803.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 689.00	
3	FRONT BUMPER CLOSING ELEMENT - CENTER	1	\$ 263.00	
4	FRONT BUMPER ADAPTER - LH / RH <i>X</i>	2	\$ 94.00	
5	FRONT BUMPER REINFORCEMENT - LH <i>?</i>	1	\$ 132.00	
6	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 181.00	
7	FRONT BUMPER CLOSING ELEMENT - LOWER <i>?</i>	1	\$ 248.00	
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>su</i>	1	\$ 350.00	
9	FRONT BUMPER AIR GUIDE - LH UPPER / LOWER <i>?</i>	2	\$ 100.00	
10	RADIATOR GRILLE <i>?</i>	1	\$ 2,603.00	
11	RADIATOR GRILLE BRACKET <i>?</i>	1	\$ 14.00	
12	"QUATTRO" INSCRIPTION <i>?</i>	1	\$ 110.00	
13	RADIATOR GRILLE COVER PLATE <i>X</i>	1	\$ 65.00	
14	RADIATOR GRILLE COVER CAP <i>X</i>	1	\$ 39.00	
15	RADIATOR GRILLE BRACKET <i>X</i>	1	\$ 111.00	
16	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ 1,140.00	
17	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$ 156.00	
18	FRONT BUMPER SUPPORT BRACKET - LH <i>?</i>	1	\$ 65.00	
19	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2	\$ 71.00	
20	FRONT BUMPER GUIDE SECTION - LH <i>de</i>	1	\$ 53.00	
SUB TOTAL SPARE PARTS		:	\$ 10,287.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGX 1911 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER TOP COVER <i>OK</i>	1	\$ 171.00	
22	CAUTION SIGN STICKER <i>OK</i>	1	\$ 17.00	
23	AIR CONDITIONER STICKER <i>OK</i>	1	\$ 9.00	
24	HORN LOW TONE - LH ?	1	\$ 244.00	
25	HORN BRACKET - LH ?	1	\$ 56.00	
26	FRONT PARKING AID SENSOR - INNER / OUTER <i>MISS</i>	2	\$ 598.00	
27	FRONT PARKING AID SENSOR ?	1	\$ 299.00	
28	FRONT PARKING AID SEAL RING <i>OK</i>	4	\$ 11.00	
29	FRONT BUMPER WIRING SET ?	1	\$ 648.00	
30	FRONT FENDER - LH <i>OK</i>	1	\$ 2,039.00	
31	FRONT FENDER BRACE - LH ?	1	\$ 140.00	
32	FRONT FENDER BRACKET - LH UPPER ?	1	\$ 52.00	
33	FRONT WHEEL HOUSING LINER <i>OK</i>	1	\$ 322.00	
34	FRONT WHEEL SPOILER - LH <i>OK</i>	1	\$ 196.00	
35	FRONT WHEEL SPOILER STONE CHIP GUARD - LH <i>OK</i>	1	\$ 60.00	
36	FRONT WHEEL SPOILER TRIM BRACKET - LH ?	1	\$ 29.00	
37	FRONT COVER PANEL - LH ?	1	\$ 42.00	
38	BONNET <i>OK</i>	1	\$ 6,632.00	
39	BONNET IMPACT PROTECTION - CENTER <i>OK</i>	1	\$ 53.00	
40	BONNET IMPACT PROTECTION - LH / RH <i>OK</i>	2	\$ 46.00	
SUB TOTAL SPARE PARTS		:	\$ 11,664.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.


55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGX 1911 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET STRIKER - LH ?	1	\$ 130.00	
42	BONNET LOCK ?	1	\$ 244.00	
43	FRONT FENDER COVER - LH ?	1	\$ 73.00	
44	FRONT FENDER SEAL - LH ?	1	\$ 24.00	
45	HEADLIGHT COVER - LH ?	1	\$ 52.00	
46	HEADLIGHT MOUNTING - LH ?	1	\$ 140.00	
47	HEADLIGHT - LH bu /	1	\$ 14,605.00	
48	HEADLIGHT HOSE - LH ?	1	\$ 34.00	
49	HEADLIGHT COMPENSATING PIECE ?	1	\$ 48.00	
50	HEADLIGHT COMPENSATING PIECE ?	1	\$ 48.00	
51	LIFT CYLINDER - LH ?	1	\$ 230.00	
52	LIFT CYLINDER BRACKET - LH ?	1	\$ 8.00	
53	LIFT CYLINDER HOSE ?	1	\$ 208.00	
54	LOCK CARRIER MOUNTING ?	1	\$ 1,448.00	
55	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 27.00	
56	READY-MIX COOLANT ?	6	\$ 326.00	
57	RADIATOR AIR GUIDE - LH ?	1	\$ 50.00	
58	RADIATOR AIR GUIDE - UPPER ?	1	\$ 39.00	
59	FRONT ALUMINIUM RIM 1/2 repair - polish	1	\$ 2,502.00	
60	FRONT ALUMINIUM RIM RUBBER VALVE X	1	\$ 4.00	
SUB TOTAL SPARE PARTS		:	\$ 20,240.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.




55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGX 1911 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
61	FRONT NUMBER PLATE ?	S/N	\$	60.00	
62	SUNDRIES ?		\$	500.00	
TOTAL SPARE PARTS		:	\$	42,751.00	
TOTAL LABOUR CHARGES		:	\$	14,472.00	
GRAND TOTAL		:	\$	57,223.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: *Rasm - 4p 90010068*
: *01/03/23 @ 1500*
:
: *7 days*
: *EXCESS: TBA*
:
: *Revert*
: *Range before paint*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	415F
Vehicle Details	
Vehicle No.:	SGX1911E
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Mar 2023
Vehicle Make:	AUDI
Vehicle Model:	A7 SPORTBACK 2.0 TFSI QU (180KW)
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	DLH066891
Chassis No.:	WAUZZZF22LN013749
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$58,902.00
Original Registration Date:	30 Oct 2020
First Registration Date:	30 Oct 2020
Transfer Count:	0
Actual ARF Paid:	\$78,024.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2030
PARF Rebate Amount:	\$58,518.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2030
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$40,301.00
COE Rebate Amount:	\$30,864.00
Total Rebate Amount:	\$89,382.00

Audi A7 Sportback Mild Hybrid 2.0A TFSI Quattro S-tronic

Overview

Financial

Accessories

Similar

Research

Photos

Map

CARS & COFFEE

CERTIFIED PRE-OWNED

Price **\$228,000**

Depreciation  \$27,560 /yr
[View models with similar depre](#)

Reg Date 07-Jan-2020
(6yrs 10mths 8days COE left)

Mileage 46,488 km (14.8k /yr)

Manufactured  2019

Road Tax  \$1,194 /yr

Transmission Auto

Dereg Value  \$83,205 as of today ([change](#))

Fuel Type Petrol-Electric

COE  \$36,000

OMV  \$58,902

Engine Cap 1,984 cc

ARF  \$78,024

Curb Weight  1,825 kg

Power 180.0 kW (241 bhp)