

DATE : 01.03.2023

TO : **FIRST CAPITAL**
 VEHICLE NO : **SKK 238 T**
 MODEL : **KIA STONIC**
 DATE OF ACCIDENT : 28.02.2023
 DATE OF REG : 29.10.2020
 CHASSIS : KNAD6811VL6346809

thron

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Distorted</i>	1	\$ 608.50	\$ 608.50
2	REAR BUMPER SIDE UPPER <i>RH Distorted</i>	2	\$ 198.60	\$ 397.20
3	REAR BUMPER DIFFUSER <i>Distorted</i>	1	\$ 563.20	\$ 563.20
4	REAR BUMPER REFLECTOR <i>Cracked</i>	2	\$ 98.50	\$ 197.00
5	REAR BUMPER TOWING COVER <i>Distorted</i>	1	\$ 38.50	\$ 38.50
6	REAR BUMPER SENSOR <i>2 pieces damaged</i>	4	\$ 152.30	\$ 609.20
7	REAR BUMPER SENSOR HOLDER <i>new</i>	4	\$ 38.60	\$ 154.40
8	REAR BUMPER SENSOR WIRE HARNESS <i>new</i>	1	\$ 398.70	\$ 398.70
9	REAR BUMPER SIDE RETAINER <i>Damaged</i>	2	\$ 68.90	\$ 137.80
10	REAR BUMPER REINFORCEMENT <i>Cracked</i>	1	\$ 487.50	\$ 487.50
11	REAR BUMPER REINFORCEMENT BRACKET <i>Best</i>	2	\$ 135.80	\$ 271.60
12	REAR BUMPER BRACKET <i>Damaged</i>	5	\$ 42.90	\$ 214.50
13	TAILGATE <i>Distorted</i>	1	\$ 1,178.90	\$ 1,178.90
14	TAILGATE LAMPS <i>LH cut</i>	2	\$ 402.30	\$ 804.60
15	TAILGATE LAMPS INNER SEALER <i>new</i>	2	\$ 380.00	\$ 760.00
16	TAILGATE LOGO <i>3 pieces</i>	1	\$ 89.20	\$ 89.20
17	TAILGATE EMBLEM 'GDI'	1	\$ 79.60	\$ 79.60
18	TAILGATE DETECTOR <i>Cracked</i>	1	\$ 185.30	\$ 185.30
19	TAILGATE NUMBER PLATE LAMP <i>LH Cracked</i>	2	\$ 58.90	\$ 117.80
20	TAILGATE STOPPER <i>new</i>	1	\$ 25.00	\$ 25.00
21	TAILGATE EMBLEM 'STONIC' <i>new</i>	1	\$ 85.90	\$ 85.90
22	TAILGATE DAMPER <i>new</i>	2	\$ 185.20	\$ 370.40
23	TAILGATE INNER TRIM <i>distorted</i>	1	\$ 298.70	\$ 298.70
24	TAILGATE INNER LOCK <i>Damaged</i>	1	\$ 168.30	\$ 168.30
25	TAILGATE LOCK CATCH <i>new</i>	1	\$ 36.00	\$ 36.00
26	TAILGATE WEATHERSTRIP <i>new</i>	1	\$ 162.70	\$ 162.70
27	TAILLAMP <i>new LH cracked</i>	2	\$ 468.90	\$ 937.80
28	REAR FENDER INNER COWLING <i>new</i>	2	\$ 115.20	\$ 230.40

198.60
366.
304.60
100
80
402.30
58.90
468.90

TO : FIRST CAPITAL
 VEHICLE NO : SKK 238 T
 MODEL : KIA STONIC
 DATE OF ACCIDENT : 28.02.2023
 DATE OF REG : 29.10.2020
 CHASSIS : KNAD6811VL6346809

29	REAR FENDER INNER TRIM <i>RT behind</i>	2	\$ 358.60	\$ 717.20 <i>358.60</i>
30	REAR END PANEL <i>Dented</i>	1	\$ 489.30	\$ 489.30
31	REAR END PANEL TOP GARNISH <i>Del</i>	1	\$ 135.80	\$ 135.80
32	REAR FLOOR PANEL BOTTOM COVER GARNISH <i>del</i>	1	\$ 253.60	\$ 253.60
33	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 315.90	\$ 315.90
34	REAR STORAGE COVER BOARD <i>new</i>	1	\$ 436.90	\$ 436.90
35	REAR SIELNCER BOX <i>new</i>	1	\$ 758.90	\$ 758.90
36	REAR SIELNCER BOX INSULATOR <i>new</i>	1	\$ 98.50	\$ 98.50
37	REAR EXHAUST GASKET (SET) <i>2 NP</i>	1	\$ 35.00	\$ 35.00
38	REAR EXHAUST MOUNTING <i>new</i>	4	\$ 30.00	\$ 120.00

7053-40
6348.06

TOTAL PRICE \$ 12,969.80
 LESS 10% \$ 1,296.98
 SUB TOTAL PRICE \$ 11,672.82

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE WITH CASING <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
3	TAILGATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
4	TAILGATE EMBLEM 'C & C' (SPECIAL TYPE) <i>new</i>	1	\$ 80.00	\$ 80.00
5	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
6	TAILGATE WINDSCREEN INNER SHIELD <i>new</i>	1	\$ 60.00	\$ 60.00
7	TAILLAMP CLIP (SET) <i>new</i>	2	\$ 40.00	\$ 80.00
8	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	2	\$ 40.00	\$ 80.00
9	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	2	\$ 40.00	\$ 80.00
10	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00
11	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
12	REAR FLOOR PANEL BOTTOM COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
13	REVERSE CAMERA <i>Damaged</i>	1	\$ 450.00	\$ 450.00

TOTAL \$1,230.00

650

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

TO : **FIRST CAPITAL**
 VEHICLE NO : **SKK 238 T**
 MODEL : **KIA STONIC**
 DATE OF ACCIDENT : **28.02.2023**
 DATE OF REG : **29.10.2020**
 CHASSIS : **KNAD6811VL6346809**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	8w
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	8w
3	TUFF COAT	\$ 350.00	60
4	REMOVE AND REFIX INTERIOR UPHOLSTERY TO FACILITATE REPAIR	\$ 200.00	60
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	50
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 150.00	50
8	TRANSFER TAILGATE MECHANISM	\$ 80.00	60
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	/
10	CONDUCT WATER LEAKAGE TEST	\$ 100.00	x
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 120.00	x
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	+

TOTAL \$ 5,290.00

ESTIMATE REPORT

TOTAL PARTS COST : \$12,902.82
 TOTAL LABOUR COST : \$5,290.00
 TOTAL REPAIR COST : \$18,192.82

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King -

W/S 02/03/23.

06 Days.

total 8998.06

W/S: 7.2K

7.214