

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 18 Apr 2023

Preliminary Advice

Insured Vehicle No	: FBH3603A	Accident Date	: 17/02/2023
TP Vehicle No	: SDP1236Z	Assignment Date	: 01/03/2023
Make	: TOYOTA SIENTA	Est. Duration of Repair	: 4
Date of Inspection	: 02/03/2023		
Inspection At	: THIAM HENG HUAT PTE LTD (SIN MING) 176 SIN MING DRIVE, #05-14 SINGAPORE 575721		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,643.28
Revised Amount	:S\$	3,009.08
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,009.08
 Lump Sum Repair	 :S\$	 2,400.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	112,000.00
COE / PARF Rebate	:S\$	39,697.00
Salvage Value	:S\$	
Margin for Repair	:S\$	72,303.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.