

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 AIG BUILDING, SINGAPORE 079120
 TEL: 64193000 FAX: 68357416
 ATTN: Motor Claim Department

Estimate No: EST2300090
Date: 27 Feb 2023
Veh Reg No: S JL6916L
Make/Model: TOYOTA COROLLA
 ALTIS 1.6 AUTO
Chasis No: MR053ZEE106122801
Reg. Date: 09/12/2008
Your Ref No: S JL9669E

Claim Type: Third Party
Accident Date: 25/02/2023

Estimate Repair Cost to Vehicle No :S JL6916L

Quantity	Description	List Price <u>S\$</u>	Amount <u>S\$</u>
List Price			
1	1 PC FRT BUMPER	679.10	
2	1 PC FRT BUMPER REINFORCEMENT	338.20	
3	2 PCS FRT BUMPER SIDE RETAINER	137.40	
4	1 PC FRT FOG LAMP RH	322.80	
5	1 PC FRT FOG LAMP COVER RH	70.70	
6	1 PC FRT FOG LAMP LH	322.80	
7	1 PC FRT FOG LAMP COVER LH	70.70	
8	1 PC FRT BUMPER GRILLE	169.40	
9	1 PC FRT BUMPER TOP RUBBER	59.40	
10	1 PC FRT BUMPER SPONGE	184.20	
11	1 PC FRT SUPPORT PANEL	885.60	
12	1 PC BONNET LOCK	163.70	
13	1 PC FRT BRACE PANEL	101.20	
14	1 PC HEADLAMP RH	888.60	
15	1 PC HEADLAMP LH	888.60	
16	1 PC FRT GRILLE	429.90	
17	1 PC FRT GRILLE EMBLEM	79.90	
18	1 PC AIRCON CONDENSER	1,947.40	
19	2 PCS AIRCON CONDENSER SIDE TRIM	123.20	
20	1 PC AIRCON DISCHARGE PIPE	342.10	
21	1 PC AIRCON RECEIVER PIPE	266.90	
22	1 PC RADIATOR	2,585.10	
23	1 PC RADIATOR FAN COWLING	353.20	
24	1 PC RADIATOR FAN	195.10	
25	1 PC RADIATOR FAN MOTOR	608.80	
26	1 PC RADIATOR UNDER COVER	260.30	
		12,474.30	
		Less 25%	9,355.78
Special Net			
27	1 SET FRT BUMPER GRILLE CLIPS	30.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2300090
Date: 27 Feb 2023
Veh Reg No: SJL6916L
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Chasis No: MR053ZEE106122801
Reg. Date: 09/12/2008
Your Ref No: SJL9669E

Claim Type: Third Party
Accident Date: 25/02/2023

Estimate Repair Cost to Vehicle No :SJL6916L

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
28	1 SET FRT BUMPER CLIPS	40.00	
29	1 PC FRT NUMBER PLATE	50.00	
30	1 SET FRT GRILLE CLIPS	30.00	
31	1 SET RADIATOR UNDER COVER CLIPS	40.00	
		190.00	190.00
	Labour		
32	1 TO CHECK WIRING	50.00	
33	1 TO RET AIRCON GAS	120.00	
34	1 TO SPRAY PANEL SEALANT	100.00	
35	1 TO SPRAY PAINTING DAMAGED PORTION, INCLUDING SUPPLY OF PAINT MATERIALS SUCH AS MASKING TAPE, SAND PAPERS, PRIMER, POLISHING COMPOUND AND CHEMICAL ETC.	1,000.00	
36	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00	
		2,270.00	2,270.00
		Total	S\$ 11,815.78
		Add GST @ 8%	945.26
		Total Amount Payable	<u>S\$ 12,761.04</u>

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND SEVEN HUNDRED SIXTY ONE AND CENTS FOUR ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE