



JACK CARS

DRIVE WITH ASSURANCE

ESTIMATE

DATE OF ACCIDENT : 01/03/2023
VEHICLE : SMQ6550X
MAKE & MODEL : TOYOTA SIENTA
INSURANCE : ALLIANZ
SURVEYOR : LKK ADRIAN

PARTS		AMOUNT
1.	BONNET <i>Dented</i> 450	\$ 1800 ✓
2.	BONNET INSULATOR <i>Crushed</i> 210	\$ 210 ✓
3.	BONNET WEATHERSTRIP <i>RENEW</i>	\$ 330 +
4.	BONNET LOCK <i>Jammed</i> 95	\$ 320 ✓
5.	BONNET HINGE - LEFT & RIGHT <i>Bent</i> 150	\$ 250 ✓
6.	FRONT FENDER - LEFT <i>Distorted</i> 350	\$ 980 ✓
7.	FRONT FENDER - RIGHT 350	\$ 980 ✓
8.	FRONT FENDER BRACKET - LEFT & RIGHT <i>RENEW</i>	\$ 300 +
9.	HEADLIGHT - LEFT <i>Crushed</i> 1300 2300	\$ 2300 ✓
10.	HEADLIGHT - RIGHT <i>Crushed</i> 1300 2300	\$ 2300 ✓
11.	HEADLIGHT TOP BRACKET - RIGHT <i>NEW</i>	\$ 110 X
12.	HEADLIGHT TOP BRACKET - LEFT <i>NEW</i>	\$ 100 X
13.	HEADLIGHT LOWER BRACKET - RIGHT <i>RENEW</i>	\$ 110 +



JACK CARS

DRIVE WITH ASSURANCE

14.	HEADLIGHT LOWER BRACKET - LEFT	New		\$ 110	X
15.	FRONT BUMPER	Rehd	480 900	\$ 900	/
16.	FRONT BUMPER CHROME GARNISH	enhd	180	\$ 350	/
17.	FRONT BUMPER GARNISH	enhd	300	\$ 520	/
18.	FRONT BUMPER GRILLE GARNISH	New		\$ 380	+
19.	FRONT BUMPER BRACKET - LEFT & RIGHT	Rehd	150	\$ 200	/
20.	FRONT BUMPER SPONGE	enhd	75	\$ 180	/
* 21.	FOG LAMP COVER	New	75	\$ 310	+
22.	INTAKE MANIFOLD	Rehd Repeated		\$ 2500	X
* 23.	FRONT REINFORCEMENT	Dented.	250	\$ 1800	/
24.	FRONT REINFORCEMENT TOP COVER	Rehd		\$ 230	-
25.	CENTRE BRACKET	New		\$ 310	X
* 26.	RADIATOR	enhd	600 910	\$ 910	/
27.	RADIATOR FAN COVER	New		\$ 420	X
* 28.	RADIATOR FAN MOTOR (2)	New	500	\$ 500	X
* 29.	RADIATOR FAN FIN (2)	New	220	\$ 220	X
* 30.	AIRCON CONDENSOR	Best.	580 930	\$ 930	/
* 31.	AIR BOX	enhd.	440	\$ 440	/
* 32.	INTAKE MANIFOLD	New	650	\$ 720	X
33.	Toyota "HONDA" EMBLEM	Missing	7400 65	\$ 65	-
+10%: 8140					



SPECIAL NETT		
1.	FRONT NUMBER PLATE & COVER <i>Atta-vented</i>	\$ 95 <i>50</i>
2.	CLIPS , RIVETS & SCREWS <i>all</i>	\$ 100 <i>30</i>
3.	TOW HOOK COVER <i>all m</i>	\$ 75 <i>+</i>
4.	COOLANT <i>all</i>	\$ 100 <i>50</i>
3.	AIRCON GAS <i>all</i>	\$ 120 <i>50</i>
LABOUR		
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	\$ 2500 <i>1200</i>
2.	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.	\$ 2200 <i>800</i>
3.	TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE	\$ 250 <i>30</i>
4.	TO REMOVE & REINSTALL SENSORS	\$ 200 <i>+</i>
5.	ANTI RUST TREATMENT	\$ 200 <i>60</i>
PARTS + 10 %:		\$ 24,293.50
SPECIAL NETT :		\$ 490
LABOUR :		\$ 5,350
TOTAL :		\$ 30,133.50
8% GST :		\$ 2,410.68
GRAND TOTAL :		\$ 32,544.18

Acknowledged by Repairer
Signature:
Date:

*total: 10410-
4/5: 8.3K.*