

## **ESTIMATE**

**DATE OF ACCIDENT** : 01/03/2023

**VEHICLE**: SMQ6550X

MAKE & MODEL: TOYOTA SIENTA

**INSURANCE**: ALLIANZ

**SURVEYOR**: LKK ADRIAN

	PARTS	AMOUNT
1.	BONNET Devted	\$ 1800
2.	BONNET INSULATOR Compled.	\$ 210
3.	BONNET WEATHERSTRIP ?	\$ 330 7
4.	BONNET LOCK Jamed	\$ 320
5.	BONNET HINGE - LEFT & RIGHT But.	\$ 250 /
6.	FRONT FENDER - LEFT 2 Distorted	\$ 980 _
7.	FRONT FENDER - RIGHT	\$ 980
8.	FRONT FENDER BRACKET – LEFT & RIGHT	\$ 300 ?
9.	HEADLIGHT - LEFT cruchd	\$ 2300
10.	HEADLIGHT - LEFT Cruchd  HEADLIGHT - RIGHT Cruchd	\$ 2300
11.	HEADLIGHT TOP BRACKET - RIGHT 2 M	\$ 110 \( \tau
12.	HEADLIGHT TOP BRACKET - LEFT New	\$ 100 }
13.	HEADLIGHT LOWER BRACKET - RIGHT ?	\$ 110 ?



14.	HEADLIGHT LOWER BRACKET - LEFT	\$ 110 .7
15.	FRONT BUMPER Delad	\$ 900 /
16.	FRONT BUMPER CHROME GARNISH and	\$ 350 /
17.	FRONT BUMPER GARNISH Cull	\$ 520
18.	FRONT BUMPER GRILLE GARNISH we m	\$ 380 +
19.	FRONT BUMPER BRACKET - LEFT & RIGHT 2 d	\$ 200 /
20.	FRONT BUMPER SPONGE Combd	\$ 180 /
21.	FOG LAMP COVER ME	\$ 310 +
22.	INTAKE MANIFOLD Repented	\$ 2500 7.
23.	FRONT REINFORCEMENT	\$ 1800 ?
24.	FRONT REINFORCEMENT TOP COVER 2	\$ 230 _
25.	CENTRE BRACKET 7	\$ 310 7
26.	RADIATOR ?	\$ 910 ?
27.	RADIATOR FAN COVER 7	\$ 420 ?
28.	RADIATOR FAN MOTOR (2)	\$ 500 7
29.	RADIATOR FAN FIN (2)	\$ 220 7
30.	AIRCON CONDENSOR ?	\$ 930 ?
31.	AIR BOX 7	\$ 440 7
32.	INTAKE MANIFOLD	\$ 720 ?
33.	"HONDA" EMBLEM Missing	\$ 65 /
	V	







	SPECIAL NETT	(A)
1.	FRONT NUMBER PLATE & COVER And Dester	\$ 95
2.	CLIPS , RIVETS & SCREWS	\$ 100 30
3.	TOW HOOK COVER M	\$75 <b>+</b>
4.	COOLANT	\$ 100 \$ 2
3.	AIRCON GAS M	\$ 1 <del>20</del> Su
k yeszentés	LABOUR	
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	\$ 2500 / 2
2.	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.	\$ 2200 &
3.	TO CHECK LIGHTING SYSTEM , WIRING & REWIRE	\$ 250 3
4.	TO REMOVE & REINSTALL SENSORS	\$ 200 \( \mathcal{L} \)
5.	ANTI RUST TREATMENT	\$ 200 60
	Adria Lin PARTS + 10 %:	\$ 24,293.50
	SPECIAL NETT:	\$ 490
	me Anthrist LABOUR:	\$ 5,350
The Control of the Co	LKK Auto Consultants hence notify the Repairer of the following:	\$ 30,133.50
	• To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation  Exum: \$2000 8% GST:	\$ 2,410.68
	Third party survey is on a "Without Prejudice" basis     No illegal modification(s) is allowed     Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	\$ 32,544.18

Acknowledged by Repairer

Signature:

Date:

## > Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

Owner ID Type:	Company
Owner ID:	043G
Vehicle Details	
Vehicle No.:	SMQ6550X
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Mar 2023
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA HYBRID 1.5G CVT
Primary Colour:	Red
Manufacturing Year:	2019
Engine No.:	1NZR791373
Chassis No.:	NHP1707175225
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$28,186.00
Original Registration Date:	28 Nov 2019
First Registration Date:	28 Nov 2019
Transfer Count:	0
Actual ARF Paid:	\$21,461.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2029
PARF Rebate Amount:	\$16,095.00
Intended COE Rebate Details	
COE Expiry Date:	27 Nov 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$27,000.00
COE Rebate Amount:	\$18,180.00
Total Rebate Amount:	\$34,275.00

The information contained herein is correct as at 03 Mar 2023

