



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23002251/Kvy3m4 Date: 15/03/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGE 808C	Veh. Inspected	SLR 1660B	
Policy No.		Coverage (\$)	0.00	
Claim No.	AVS23/0741	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	02/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CHR (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	-	
Chassis No.	ZYX102016579	Colour	METALLIC BLACK	
Odometer	73135 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	FALKEN	8 mm	
L/H Front Tyre	225/50 R18	FALKEN	8 mm	
R/H Rear Tyre	225/50 R18	FALKEN	8 mm	
L/H Rear Tyre	225/50 R18	FALKEN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/02/2023	Inspection Date	02/03/2023	
Survey held at	RC AUTO 160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)REGISTRATION DATE: 01 AUG 2017 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	