

PRESTIGE APPRAISER SERVICES

Vehicle No : FBF 2200 X

Our Ref : PS/0111/01/23

Qty	Descriptions <u>LIST ITEMS</u>	Conditions	Repairer's Est.	Our Revised.
			\$	\$
1	front wheel rim repair	denetd/cut	520.00	520.00 X
1	front brake disc	denetd/warped	189.00	189.00 X
1	front mudguard	broken	215.00	215.00 X
1	front fork	denetd/warped	640.00	640.00 X
1	front under bracket	denetd	102.00	102.00 X
1	steering cone	denetd	89.00	89.00 X
1	headlamp	cracked	285.00	285.00 X
1	headlamp bracket	denetd	62.00	62.00 X
2	signal lamp X	scratched	196.00	196.00 X
1	headlamp lower garnish	denetd	95.00	95.00 X
2	signal lamp garnish	denetd	90.00	90.00 X
1	headlamp cowlings	denetd	105.00	105.00 X
1	front visor	missing/dislodged	89.00	89.00 X
1	front visor garnish	denetd	65.00	65.00 X
1	front visor garnish stay	denetd	42.00	42.00 X
2	headlamp side panel	denetd	96.00	96.00 X
1	front splash shield	denetd	63.00	63.00 X
1	front splash shield body garnish	denetd	58.00	58.00 X
1	handle bar	denetd	215.00	215.00 X
2	handle grip	necessary	76.00	76.00 X
2	handle balancer	sliced	72.00	72.00 X
2	lever	sliced	170.00	170.00 X
1	R/H centre body garnish	denetd	103.00	103.00 X
1	R/H step garnish	denetd	128.00	128.00 X
1	R/H step garnish lower garnish	denetd	106.00	106.00 X
1	R/H step garnish seal	denetd	45.00	45.00 X
1	R/H rear foot rest	denetd	72.00	72.00 X
1	R/H rear body garnish	denetd	89.00	89.00 X
1	R/H rear body garnish cover	denetd	75.00	75.00 X
1	engine inner cover	denetd	122.00	122.00 X
1	engine outer cover	denetd	138.00	138.00 X
1	engine lower cover	denetd	135.00	135.00 X
1	side stand	denetd	85.00	85.00 X
1	main stand	denetd	92.00	92.00 X
2	mirror	sliced	164.00	164.00 X
1	R/H step garnish	denetd	128.00	128.00 X
1	R/H step lower garnish	denetd	106.00	106.00 X
1	R/H step garnish seal	denetd	45.00	45.00 X
1	R/H centre body garnish	denetd	89.00	89.00 X
1	R/H centre body garnish cover	denetd	65.00	65.00 X
1	R/H rear foot rest	sliced	72.00	72.00 X
1	R/H rear body garnish	denetd	102.00	102.00 X
1	rear mudguard	denetd/cut	98.00	98.00 X
1	radiator cover	denetd	85.00	85.00 X
1	exhaust muffler	denetd	620.00	620.00 X
1	exhaust heat shield	denetd	86.00	86.00 X
1	rear wheel rim	serviceable	550.00	
1	front brake caliper	serviceable	265.00	
			7,199.00	
			\$	\$
			Less 10%	6,384.00
			Balance c/f	638.40
				5,745.60

PRESTIGE APPRAISER SERVICES

Vehicle No : FBF 2200 X

Our Ref : PS/011/01/23

Qty	Descriptions	Conditions	Balance b/d	\$	Repairer's Est.	Our Revised.
	<u>SANETT ITEMS</u>					
1	front video camera	broken			400.00	150 200.00
1	front tyre X 11	wall cut			200.00	150.00 X
1	front number plate	missing/dislodged			35.00	25.00
1	rear box	dented/cut			500.00	200 450.00
1	rear box bracket repair	dented			180.00	140.00 X

Labour Charges & Misc

To dismantle & replace damaged parts, panel beat where necessary.

To putty, apply primer & spray-paint on the affected portion.

To align main body frame.

Transportation charges. X 11

	660.00	450 580.00
	600.00	250 500.00
	280.00	200 250.00
	60.00	50.00 X
\$	<u>10,114.00</u>	\$ <u>8,170.60</u>

301680

375.00

900.00

4291.80

206

3433.44

45-\$3,400/4 days

Note: The repairer has agreed to undertake the repairs at our adjusted amount of \$6,500.00 lump sum corresponding to supply of parts, labour and spray-painting charges.

Under normal circumstances, the estimated repair period would be **FOUR (4)** days.

Pursuant to your instruction we have not authorised repairs on your behalf.

PRESTIGE APPRAISER SERVICES

LOUIS S CNG CAE AMIMI (UK)

Licensed Appraiser

Dip. MTM. Automotive Engineer