

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

Claim Details
Case Ref. No. : OD/032023/6064
Date : 16-03-2023
Accident Date : 28-02-2023

Vehicle Details

Make & Model : Kia CERATO 1.6(A) SX
Chassis No : KNAF3416MK5030324
Registration No : SMK1639P

S/N	Description	Qty	Amount (\$\$)	
1	ENGINE ECU ?	1.00	\$900.00	?
2	ABS PUMP ?	1.00	\$1,400.00	?
3	STARTER ?	1.00	\$320.00	?
4	ALTERNATOR ?	1.00	\$650.00	?
5	RH HEADLAMP ECU ?	1.00	\$960.00	?
6	LH HEADLAMP ECU ?	1.00	\$960.00	?
7	RADIATOR FAN MOTOR ?	1.00	\$300.00	?
8	WIPER MOTOR ?	1.00	\$180.00	?
9	ENGINE WIRE HARNESS ?	1.00	\$1,200.00	?
10	DASHBOARD WIRE HARNESS ?	1.00	\$1,700.00	?
11	FRONT RH SEAT BELT mouldy	1.00	\$300.00	✓
12	FRONT LH SEAT BELT mouldy	1.00	\$300.00	✓
13	STEERING WHEEL mouldy	1.00	\$900.00	✓
14	AIRBAG IMPACT SENSOR Hw	1.00	\$40.00	X
15	AIRBAG ECU ?	1.00	\$740.00	?
16	AIRCON BLOWER UNIT Hw	1.00	\$160.00	X
17	BCM MODULE ?	1.00	\$1,800.00	?
18	METER Hw	1.00	\$1,600.00	X
19	DRIVER SEAT ELECTRIC CONTROL MODULE ?	1.00	\$400.00	?
20	DRIVER SEAT ELECTRIC CONTROL MODULE ?	1.00	\$500.00	?
21	PASSENGER SEAT ELECTRIC CONTROL MODULE ?	1.00	\$400.00	?
22	PASSENGER SEAT ELECTRIC CONTROL MODULE ?	1.00	\$500.00	?
23	DRIVER SEAT MOTOR ASSY NO.1 (HEIGHT) ?	1.00	\$180.00	?
24	DRIVER SEAT MOTOR ASSY NO.2 (SLIDE) ?	1.00	\$180.00	?
25	ELECTRONIC POWER STEERING CONTROL MODULE (EPS) ?	1.00	\$450.00	?
26	FRONT DOOR LOCK Hw	2.00	\$940.00	X
27	REAR DOOR LOCK Hw	2.00	\$760.00	X
28	FRONT DOOR POWER WINDOW MOTOR Hw	2.00	\$260.00	X
29	REAR DOOR POWER WINDOW MOTOR Hw	2.00	\$200.00	X
30	USB CHARGES MODULE (@CENTER CONSOLE) Hw	1.00	\$1,100.00	X

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

31	INTERIOR CARPETS WITH UNDERLAY FELTS <i>mouldy</i>	1.00	\$650.00	✓
32	EXHAUST CATALYTIC <i>HW</i>	1.00	\$1,900.00	X
33	CARPET (REMOVEABLE) <i>mouldy</i>	4.00	\$1,000.00	✓

\$23,830.00

Margin: 10%

\$2,383.00

\$26,213.00

34	ENGINE OIL	6.00	\$150.00 80/-
35	ATF	4.00	\$140.00 100/-
36	COOLANT	1.00	\$80.00 50/-
37	TO REFILL AIRCON GAS	1.00	\$150.00 ?
38	TO RESET AIRBAG SYSTEM	1.00	\$380.00 ?
39	TO RESET METER READING SYSTEM	1.00	\$380.00
40	TO RESET ENGINE ECU SYSTEM	1.00	\$380.00 } 380/-
41	TO REMOVE AND REFIX EXHAUST ASSY	1.00	\$380.00 HW
42	TO REMOVE SEAT LEATHER AND WRAP SEAT LEATHER	1.00	\$700.00 500/-
43	TO REMOVE AND REFIX FLOOR MAT	1.00	\$800.00 400/-
44	TO CLEAN AND DRY SEAT SPONGE AND FLOOR SPONGE	1.00	\$500.00 400/-
45	TO REPLACE PARTS	1.00	\$880.00 ?

Subtotal w/o GST:

\$31,133.00

17/03/2023 @ 1600h

HW Subme

10 dgs. (estimated)

Excess IBA.

you

LKK Auto

Check and dismantle
 for resurvey with old
 parts.

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair (Supplementary)

Attention To : Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

Claim Details

Case Ref. No. : OD/032023/6064
Date : 16-03-2023
Accident Date : 28-02-2023

Vehicle Details

Make & Model : Kia CERATO 1.6(A) SX
Chassis No : KNAF3416MK5030324
Registration No : SMK1639P

S/N	Description	Qty	Amount (\$)
1	THROTTLE BODY ?	1.00	\$350.00 ?
2	SPARK PLUG ?	4.00	\$40.00 ?
3	PLUG COIL ?	4.00	\$280.00 ?
4	FRONT DISC ROTOR ?	2.00	\$300.00 ?
5	FRONT BRAKE PAD HH	1.00	\$110.00 X
6	REAR DISC ROTOR ?	2.00	\$320.00 ?
7	REAR BRAKE PAD HH	1.00	\$90.00 X
8	FRONT BUMPER RH FOG LAMP ?	1.00	\$170.00 ?
9	FRONT BUMPER LH FOG LAMP ?	1.00	\$170.00 ?
10	FRONT BUMPER RH DAYLIGHT ?	1.00	\$60.00 ?
11	FRONT BUMPER LH DAYLIGHT ?	1.00	\$60.00 ?
12	FRONT BUMPER PARKING SENSOR ?	4.00	\$400.00 ?

\$2,350.00

Margin: 10%

\$235.00

\$2,585.00

Subtotal w/o GST:

\$2,585.00

Issued by Iswan

This is a computer-generated document. No signature is required.