



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC23002257/Avy3e2

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 19/05/2023

ATTN: EILEEN LEE

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMZ 9479C	Veh. Inspected	SLP 9569R
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1211445-003	Excess (\$)	0.00
Assign From	ANNA YEO	Assign Date	01/03/2023

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GK81103015	Colour	BLACK
Odometer	136411 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	ARIVO	6 mm
L/H Front Tyre	185/60 R15	ARIVO	6 mm
R/H Rear Tyre	185/60 R15	ARIVO	6 mm
L/H Rear Tyre	185/60 R15	ARIVO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/02/2023	Inspect Date / Time	02/03/2023 (12:49 PM)
Survey held at	AUTO UNITED SG PTE LTD 13 KAKI BUKIT ROAD 4, #03-29, BARTLEY BIZ CENTRE, SINGAPORE 417807		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 11 Working Days