



1

of 2 ?



100%



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref: CS/SMO23002258/Awy3

50 RAFFLES PLACE #03-03

Date: 02/03/2023

SINGAPORE LAND TOWERSINGAPORE 048623

Code: SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 9592D	Veh. Inspected	SKW 9323H
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2300890/RUC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	02/03/2023

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	01/03/2023	Inspection Date	02/03/2023
Survey held at	SPEEDWERKZ PTE LTD 1 KAKI BUKIT AVE 6 #01-73, AUTOBAY @KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--