

A&S, P.L.C. BY:

REF:

CC4/AIS23002260/Dy³

ASSIGNMENT

From:

Estimated Cost:

Date:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

ROB Sept 2024
Sept / 2014

Yr Regn:

C.C. 779

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

N522E034575

JYARN258000002129

Good / Fair / Poor / Burnt

Inorder / Jammed / Leaked / Burnt or

Inorder / Jammed / Leaked / Burnt or

Nil / S/Rim / STD A/Rim or

F:

R:

120/70 R17

180/55 R17

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Consistent?: Yes or No

Consistent?: Yes or No

Res.: Yes or No

3 Val.: Yes or No

Date / Time

Action / Instruction

AIS SJK 747C

MV 12K

LTA 682.00

*FRL 11.3K

Date/Time, File Pass 10?

Date/Time, File Return 10?



Prel. Report



Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Report Format:

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 28 February 2023

To : LKK

Attn : Bryan

Tel : 97237799

VEHICLE NO : FBJ 7104L

ACCIDENT DATE: 21 February 2023

Yamaha FZ8

Description	Qty	Quotation \$
1 Handle Bar <i>HN</i>	1	160.00 X
2 Brake Lever <i>cut</i>	1	95.00 ✓
3 Front Visor <i>broken</i>	1	280.00 ✓
4 Visor Bracket <i>st</i>	1	120.00 ✓
5 RH Mirror <i>dislodged</i>	1	98.00 ✓
6 Front Rim <i>cut</i>	1	280.00 ✓
7 Radiator Assy <i>broken</i>	1	450.00 ✓
8 Front RH Signal <i>cut</i>	1	120.00 ✓
9 Body Frame Slider <i>cut</i>	1 set	280.00 ✓
10 Fuel Tank <i>vapour</i>	1	320.00 X
11 Fuel Tank Top Cover <i>HN</i>	1	180.00 X
12 Head Lamp Assy <i>cut</i>	1	450.00 ✓
13 Head Lamp Guard - Centre <i>cut</i>	1	280.00 ✓
14 Balancer <i>cut</i>	1 set	180.00 ✓
15 Tank Pad RH <i>cut</i>	1	180.00 ✓
16 Body RH Protector <i>cut</i>	1	190.00 ✓
17 Brake Panel <i>st</i>	1	95.00 ✓
18 Footrest <i>st</i>	1	80.00 ✓
19 Footrest Bracket <i>st</i>	1	130.00 ✓
20 Akrapovic Exhaust <i>cut</i>	1	1,800.00 ✓ <i>1200.00 SH</i>
21 Spot Light <i>cut</i>	1 set	220.00 ✓
22 Rear Signal RH <i>Don</i>	1	95.00 ✓
23 Rear Foot Peg RH <i>HN</i>	1	90.00 X
24 Horn/Bracket <i>HN</i>	1	120.00 X
25 RH Front Fork <i>cut</i>	1	280.00 ✓
Sub-Total		6,573.00
Less 10%		657.30
Sub-Total		5,915.70

List 3903.00
10% 3512.70
=

SH 1200.00

VEHICLE NO : FBJ 7104L

Yamaha FZ8

Nett items

- 1 Rear box *HH*
- 2 Towing Fee x 2 trips *HH*
- 3 Remove & replace parts, align & etc
- 4 Remove & replace front rim & re-align fork tube
- 5 Putty & respray paint

280.00 x
80.00 x
280.00 200/-
180.00 80/-

400.00

400.00 120/-

Sub-Total

940.00

Nett Total

7135.70

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD

01/03/2023 @ 1200 hrs

5112.70

4/s 4,000/-

Not Authorized

L/s Hui

Tyler

4 days.

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature]