

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLV9309T
Accident Date : 28-Feb-2023

No. : 06776

Date : 02-Mar-2023

Our Ref : 023049 (AUTO & GEN) / SHIJIE

PAGE : 1

LAU ZHANG XIAN (LIU ZHANGXIAN)
BLK 468A YISHUN STREET 43
#12-59
Singapore 761468

ESTIMATED COST OF REPAIR FOR TOYOTA VIOS SMU6180J

1 pc	Front bonnet	744.20
1 pc	Front headlamp RH	535.20
1 pc	Front bumper	586.80
1 pc	Front bumper retainer RH	76.90
1 pc	Front foglamp garnish RH	84.40
1 pc	Front RH fender	688.60
1 pc	"WT-I"emblem	38.40
1 pc	Front RH fender inner liner	208.50
1 pc	Front RH door	1,310.80
1 pc	Side mirror assy RH	1,446.60

5,720.40

Less 25% : 1,430.10

1 pc	Front fender inner liner clips	4,290.30
1 pc	Front bumper clips	30.00 sn
1 pc	Front foglamp RH	30.00 sn
		180.00 sn

To rewire damaged parts and refocus
headlamp beam.

60.00

To putty and spray replaced parts

800.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,000.00

Total : S\$ 6,390.30

=====

Singapore Dollars Six Thousand Three Hundred
and Ninety and Cents Thirty Only