

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
ABS LEASING SERVICES PTE LTD

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA(GBB5409M)
Policy No:	DMCVSNW00133062203	Date of Loss:	28/02/2023
Vehicle Reg. No.:	GBH9804Y	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	YAN JINKUI	Driver (Insured):	ISLAM MD AMINUL
Make/Model:	NISSAN NV350, 2.5 PANEL VAN 5MT 5DR (M)	Vehicle Reg. Date:	19/11/2018
Vehicle Colour:	WHITE		
Engine No:	YD25038198B	Chassis No:	JN1MC2E26Z0030672
Odometer:	0 KM		
Paint Type:			<i>Not with a</i>
Total Loss?	NO		<i>L/L &</i>
Est. Duration of Repair (day)	0		<i>Minor After Paint</i>
Description of Accident/Loss	REFER TO GIA REPORT ATTACHED.		<i>12 days</i>
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

COST OF CLAIMS

	Amount
Parts	8,498.60
Miscellaneous Items	0.00
Labour	6,190.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	14,688.60
+ GST 8.00% (\$\$)	1,175.09
Nett Amount (\$\$)	15,863.69

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 Mar 2023)

Parts: N/A NISSAN NV350 2.5 PANEL VAN 5MT 5DR (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBH9804Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

GBH9804Y
TP/CHINA

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT LH DOOR	0.00	0.00	*780.00 F
2	1		*1 PC FRT LH DOOR SIDE MIRROR ASSY	0.00	0.00	*350.00 F
3	1		*1 PC FRT LH DOOR GLASS	0.00	0.00	*340.00 F
4	1		*1 PC FRT LH DOOR OUTER HANDLE	0.00	0.00	*88.00 F
5	1		*1 PC FRT LH DOOR INNER LOCK	0.00	0.00	*160.00 F
6	1		*1 PC FRT LH DOOR INNER RUBBER	0.00	0.00	*90.00 F
7	1		*1 PC LH CENTRE PANEL OUTER	0.00	0.00	*980.00 F
8	1		*1 PC LH SLIDING DOOR	0.00	0.00	*800.00 F
9	1		*1 PC LH SLIDING DOOR OUTER HANDLE	0.00	0.00	*90.00 F
10	1		*1 PC LH SLIDING DOOR ROLLER TRUCK	0.00	0.00	*450.00 F
11	1		*1 PC LH SLIDING DOOR INNER LOCK	0.00	0.00	*170.00 F
12	1		*1 PC LH SLIDING DOOR INNER RUBBER	0.00	0.00	*130.00 F
13	1		*1 PC LH SLIDING DOOR INNER TRIM BOARD	0.00	0.00	*280.00 F
14	1		*1 PC REAR LH SIDE PANEL	0.00	0.00	*1,050.00 F
15	1		*1 PC REAR LH SIDE PANEL INNER TRIM BOARD	0.00	0.00	*260.00 F
16	1		*1 PC FRT LH DOOR GLASS REGULATOR	0.00	0.00	*105.00 F
17	1		*1 PC FRT LH DOOR GLASS REGULATOR MOTOR	0.00	0.00	*360.00 F
18	1		*1 PC FRT RH DOOR	0.00	0.00	*790.00 F
19	1		*1 PC FRT RH STEP TRAY GARNISH	0.00	0.00	*68.00 F
20	1		*1 PC FRT BUMPER	0.00	0.00	*300.00 F
21	1		*1 PC FRT BUMPER RH SIDE RETAINER	0.00	0.00	*85.00 F

F=Franchise part.

Sub Total (\$\$) 7,726.00

+ Margin on L,N Items 10.00% (\$\$) 772.60

Total Parts (\$\$) 8,498.60

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

- the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TOWING (BY OWNER)	New	80.00
2	REMOVE & REFIX FRT BOTH DOOR, KNOCK & REPAIR FRT BOTH DOOR PILLARS, REMOVE & REFIX LH SLIDING DOOR, CUT, WELD & RENEW REAR LH SIDE PANEL, CENTRE DOOR PILLAR OUTER, KNOCK & REPAIR REAR LH SIDE INNER PANEL, CENTRE PILLAR INNER AND REALIGN THE SAME	New	2,200.00
3	REMOVE & REFIX FRT BOTH DOOR GLASS	New	120.00
4	REMOVE & REFIX TOP ROOF LINING, SEAT, CARPET	New	100.00
5	PUTTY & REPSRAY ON FRT BOTH DOORS, LH SLIDING DOOR, CENTRE PILLAR, REAR LH SIDE PANEL INNER & OUTER	New	1,500.00
6	RUSTPROOFING	New	90.00
7	TO REPAINT ADVERTISEMENT	New	2,100.00
Gross Labour Cost (\$\$)			6,190.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 30 Apr 2023)
 Parts: N/A NISSAN NV350 2.5 PANEL VAN 5MT 5DR (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/GBH9804Y/30/04/2023 13:03
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC LH DOOR CENTRE PILLAR INNER	By	0.00	0.00
2	1		*1 PC LH DOOR CENTRE PILLAR WHEEL MUDGUARD	nd	0.00	0.00
3	1		*1 PC TURBO COOLER COVER	CM	0.00	0.00
4	1		*1 PC SLIDING DOOR SWITCH	CM	0.00	0.00
5	1		*1 PC FRT GRILLE	m/c m	0.00	0.00
Sub Total (\$\$)						1,355.00
+ Margin on L,N Items 10.00% (\$\$)						135.50
Total Parts (\$\$)						1,490.50

F=Franchise part.

Cheng Hoe Motor Pte Ltd/GBH9804Y/30/04/2023 13:03. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	LH SIDE PANEL GLASS GUM	all 30.00 201
Sub Total (\$\$)			30.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
1	REMOVE AND REFIT LH SIDE PANEL GLASS	New	100.00 801
Gross Labour Cost (\$\$)			100.00

Cheng Hoe Motor Pte Ltd/GBH9804Y/30/04/2023 13:03. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >