



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : HSBC LIFE (SINGAPORE) PTE LTD

11/5/2023

Survey Details:

Date of loss	22-Feb-23
Date of appointment	2-Mar-23
Date of survey	3-Mar-23
Location of survey	AAK LOGISTICS SERVICES PL

Vehicle Details:

Claim Type:	Third Party Claim
Vehicle number	YQ 3301B
Make and Model	MINI CANTER FEB 21
Date of registration	18/12/2020
Excess	
Market Value	\$ 100,000.00
Part Rebate	\$ 24,993.00
Nett Loss	\$ 75,007.00

Repair details:

Initial Estimate	\$ -
------------------	------

Proposed/Revised repair cost:

Parts	
Check items (estimate)	
Labour	
Total	\$ -
Lump Sum(if applicable)	

Number of days for repair	8
----------------------------------	----------



Remarks:

No GIA Report provided. The estimate repair cost of the damaged vehicle is in the region of \$8,000.00 - \$9,000.00.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	