

 $51\; UBI\; AVE\; 1, \#02-25\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: (065)\; 62563561\;\; FAX: (065)\; 62564315\;\; FAX: (065)\; 6256415\;\; FAX: (065)\; FAX$

Immediate Advice

To: HSBC Life (Singapore) Pte. Ltd. Date: 19/06/2023

Survey Details:

Date of loss	1-Mar-23	
Date of appointment	3-Mar-23	
Date of survey	3-Mar-23	
Location of survey	SOON SAN MOTOR TRAI	DING

Vehicle Details:

Third p	arty	
SLJ2959B		
TOYOTA WISH (1798cc))
21/12/	21/12/2016	
\$	61,000.00	(est)
\$	32,815.00	(est)
\$	28,185.00	(est)
	SLJ295 TOYOT	TOYOTA WISH (1798cc 21/12/2016 \$ 61,000.00 \$ 32,815.00

Repair details:

Initial Estimate	\$ 14,495.45

Proposed/Revised repair cost:

Parts	\$ 4,722.10
Check items (estimate)	NIL
Labour	\$ 1,980.00
Supplementary	NIL
Total	\$ 6,702.10
Lump Sum(if applicable)	\$ 5,350.00

Number of days for repair	<u>6</u>



 $51\ UBI\ AVE\ 1,\#02-25\ PAYA\ UBI\ INDUSTRIAL\ PARK, SINGAPORE\ 408933\ \ TEL: (065)\ 62563561\ \ FAX: (065)\ 62564315$

Remarks:

OI REAR-ENDED TP.		

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 5,350.00	
Loss of use	NIL	
Loss of rental)	\$ 960.00	(8DAYS X \$120.00)
Loss of income	NIL	
LTA/GIA search fees	\$ 26.75	
Others	NIL	
Proposed Total	\$ 6,336.75	