

**SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63665592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 01/03/2023

User ID : JeongCH

**Section A - Accident Details**

Registration Number	SMB116K
Case Reference Number	BUS/02/23/5026
Registration Date	9/18/2009
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Yik Wei Cheng
Type of Accident	Side Swipe
Accident Date and Time	2/14/2023 6:27 PM
Accident Reported Date and Time	2/23/2023 2:10 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB116K - RIGHT FRONT PORTION SLZ4436R (TP) - INSURED WITH AIG
Prepared Date and Time	2/28/2023 7:26 PM
Chassis Number	WEB63442021000246
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$1,452.00	\$0.00
Total Spare Part Cost	\$1,342.23	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$4,384.23</b>	<b>\$0.00</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3 days
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	28/02/2023 7:34 PM	
Signature		
Remarks		

**Section C - Quotation and Accident Invoice Details**

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No litigation modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68682672

Date Generated : 01/03/2023

User ID : JeongCH

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,590.00	1060 ✓
<b>Total Labour</b>	<b>\$1,590.00</b>	

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$1,452.00	1282 ✓
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,452.00</b>	

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			SMRT STICKER	1.00	\$200.00	0.00	\$200.00	Replace	nu
4006314			SEALANT SIKAFLEX	8.00	\$37.00	0.00	\$296.00	Replace	nu
6009362	BODY RH		COVER, HEADLAMP: RH, FIBREGLASS, MB OC500	1.00	\$621.00	100.00	\$0.00	Repair	Ry
6010225	BODY RH	5017	PANEL, SKIRT: R2, FOR MB OC500 BUS	1.00	\$975.00	10.00	\$877.50	Replace	bt
6010226	BODY RH	5018	PANEL, SKIRT: R3, FOR MB OC500 BUS	1.00	\$338.10	10.00	\$304.29	Replace	bt
6010227	BODY RH	5019	PANEL, SKIRT: R4, FOR MB OC500 BUS	1.00	\$1,442.10	100.00	\$0.00	Repair	Ry
6010229	BODY RH	5021	PANEL, SKIRT: R6, FOR MB OC500 BUS	1.00	\$518.20	100.00	\$0.00	Repair	Ry
6010230	BODY RH	5022	PANEL, SKIRT: R7, FOR MB OC500 BUS	1.00	\$880.50	100.00	\$0.00	Repair	Ry
6010231	BODY RH	5023	PANEL, SKIRT: R8, FOR MB OC500 BUS	1.00	\$338.10	100.00	\$0.00	Repair	Ry
6010232	BODY RH	5024	PANEL, SKIRT: R9, FOR MB OC500 BUS	1.00	\$307.10	100.00	\$0.00	Repair	Ry
6010234	BODY RH	5026	PANEL, SKIRT: R11, FOR MB OC500 BUS	1.00	\$642.80	100.00	\$0.00	Repair	Ry
6010235	BODY RH	5027	PANEL, SKIRT: R12, FOR MB OC500 BUS	1.00	\$2,430.20	100.00	\$0.00	Repair	Ry
6009369	BODY RH		COVER, LAMP: REAR, RH, FOR MB OC500 BUS	1.00	\$1,242.00	100.00	\$0.00	Repair	Ry
<b>Total</b>					<b>\$9,972.10</b>		<b>\$1,677.79</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

SN - 496

975

338.10

1313.10

10% - 1181.79

1181.79

496

1677.79

20% - 1342.23

1060

1282

3684.23

=> 45\$3700, 3 days