

ASS. REC. BY:

REF:

ELW 23002285/kv

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s Arw 101

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 09 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Victor Vehicle: IN / OUT

Veh No: SMQ 94707 Yr Regn: 12.19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic C.C. 1597

Colour: A.P. White AC: Insured / Std / NI / NA

Sp. Reading: 31074 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRHFC 565 OKT 001166

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: 215/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 22/2/23

D.O.I. 13/3/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: _____

: Final Report

Resurvey No. of Trlp: _____

Date/Time, File Return to?

Survey Fee:

Add Fee: : Site Insp (\$

Transportation

: Interview (\$

S - RS. SI

: Tech Invs (\$

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Large empty rectangular box for additional notes or signatures.



NOT AUTHORIZED
 6/1 Day @
 Primary After Paint
 4 days
 Kenneth
 96910663

Auto 101 LLP

No. 2 Yishun Industrial St 1
 Northpoint Bizhub, #02-01
 Singapore 768159
 Tel: 67545101

DATE: 13-3-2023

REPAIR ESTIMATE

VEHICLE: SMQ 9470 Z
 MODEL: Honda Civic

S/n	Description of part	Qty	Estimate
1	Rear boot weather strip	1	Per 126.6 X
2	Rear boot lock mechanism	1	R 116.8 X
3	Rear boot lid lock sensor	1	175.3 ?
4	Rear boot logo	1	na 47.3 —
5	Tailgate emblem 'Civic'	1	na 48.6 —
6	Tailgate emblem 'i-vtec'	1	na 43.5 —
7	Rear bumper	1	Bumper 647 —
8	Rear bumper clip - set	1	na 40 —
9	Rear bumper side retainer RH/LH	2	na 96.6 X
10	Rear bumper reflector cover LH/RH	2	na 156.6 X
11	Rear bumper reinforcement	1	356.4 ?
12	Rear tail lamp panel LH	1	R 89.2 X
13	Rear tail lamp LH/RH	2	cut 535.6 —
14	Rear tail lamp clip - set	1	na 10 —
15	Rear tail lamp lower basket LH/RH	1	na 43.7 X
16	Rear end panel	1	R 440 X
17	Rear bumper bottom diffuser	1	cut 423 —
18	Rear bumper bottom diffuser chrome	1	partial 340 —
19	Rear end panel top garnish	1	na 95.6 X
20	Rear end panel top garnish clip - set	1	na 40 X
Sub-total 1			3,477.40
Discount 20%			2,781.92
21	rear end panel sealant	1	na 30.00 X
22	Car number plate rear	1	not 50.00 45.00
23	Reverse sensor	1	200.00 ?
Sub-total 2			280.00
Parts total			3,061.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour



Auto 101 LLP

No. 2 Yishun Industrial St 1
Northpoint Bizhub, #02-01

Singapore 768159

Tel: 67545101

1,000.00 *500*

24 To straighten and panel beating rear frame members. To cut/weld rear LH tail lamp and rear end panel. To remove and refit above parts.

25 To putty, re-spray painting and polish affected areas.

800.00 *600*

26 To check and rectify wiring system.

30.00 *20*

27 To remove and replace reverse sensor and check

50.00 *✓*

28 To rust proof affected areas.

nm 60.00 *X*

Labour total

1,940.00

Parts & Labour total

5,001.92

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 22/02/2023 15:33 (SGT)
Reported by Both Policyholder and Actual Driver
Date of Accident 22/02/2023 06:47 (SGT)
Exact Location of Accident Sengkang E Ave, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMQ9470Z
INSURED/POLICYHOLDER
Is company? No
Name Of Registered Owner NG CHENG KUI BENSON
NRIC No SXXXX727Z
Email Address BENSONROCKS@GMAIL.COM
Mobile Phone No (Phone) +65-93628477
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Honda
Model Civic
Variant CIVIC 1.6 VTI CVT
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1597


INSURANCE COMPANY

Name of Insurance Company Direct Asia Insurance (Singapore) Pte Ltd
Policy Number / Cover Note Number MT/00985142/01

DRIVER

Name of Driver NG CHENG KUI BENSON
NRIC No SXXXX727Z
Date Of Birth 15/06/1984
Occupation Indoor

Date of accident: 22 Feb 2023 Time: 0647hrs Location: Sengkang East Ave
 My Vehicle A: SMQ 9470 Z Vehicle B: G8K 2185 E Vehicle C: -



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22 Feb 2023 at about 0647hrs, I stopped my vehicle (SMQ9470Z) at the traffic light junction as the traffic light has turned red. Within seconds after my vehicle came to a halt, a min-van (G8K2185E) failed to apply his brake on time, resulting his vehicle to collide onto the rear of my vehicle. My vehicle back bumper was damage as a result of the collision.

- Claim OD/TP at Ah Lim Motor Claim OD/TP at other workshop Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :
 Email address :
 & myself :
 Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Zila
 Reporting Centre/Personnel's Signature
 Name:
 NRIC/FIN No.: