

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123002286/TCY3Q2**Date:** 18/07/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SNB3383Z **Insured Vehicle No :** GX4251G

Date of Loss: 24/02/2023 Nature of Claim: TP Claim No: CDMCG23000490

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNB3383Z**

Make & Model: BMW 316I, 1.6 AT D/AB 4DR ABS HID (A) Engine No: A191J849N13B16A

Reg. Date: 28/05/2015 (Man. Year: 2014) Chassis No: WBA3A16020NS38701

Colour: White Odometer: 138096 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18

Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,013.01	6,176.42	2,836.59	31.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,310.00	490.00	27.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,813.01	7,486.42	3,326.59	30.76
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	10,813.01	6,000.00	4,813.01	44.51
+ GST 8.00/8.00% (S\$)	865.04	480.00	385.04	44.51
Nett Amount (S\$)	11,678.05	6,480.00	5,198.05	44.51

INSPECTION

Date of Assignment: 02/03/2023

Date Inspected: 07/03/2023 Inspected At: Twin Wheel Auto Trading Enterprise (HQ)
38 Woodlands Road, #03-14 Woodlands Industrial Park E1
Singapore 757700

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jul 2023)
Parts:	143	BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB3383Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,450.00 FL	*1,233.25 FL
2	1		*FRONT BUMPER SIDE RETAINER	O/S Deformed/N/S Not Necessary	120.00 FL	*60.00 FL
3	1		*HEADLAMP -RH	Cracked	2,650.00 FL	*2,245.00 FL
4	1		*HEADLAMP RETAINER -RH	Not Necessary	190.00 FL	*- FL
5	1		*HEADLAMP MODULE	Not Necessary	788.90 FL	*- FL
6	1		*FRONT FENDER -RH	Bent	720.00 FL	*720.00 FL
7	1		*FRONT FENDER COWLING -RH	Torn	130.00 FL	*130.00 FL
8	1		*FRONT WHEEL BEARING -RH	Bent	355.00 FL	*260.00 FL
9	1		*FRONT WHEEL BEARING HUB-RH	Not Necessary	285.00 FL	*- FL
10	1		*FRONT KNUCKLE -RH	Bent	650.00 FL	*650.00 FL
11	1		*FRT BUMPER EMBLEM	Necessary	120.00 FL	*120.00 FL
12	1		*FRONT BUMPER SPOILER	Cut	1,450.00 FS	*650.00 FS
13	1		*FRONT SPORT RIM -RH	Cut	850.00 FS	*650.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	9,758.90 6,718.25
					- List Item Discount on L Items 10.00/10.00% (\$\$)	745.89 541.83
					Total Parts (\$\$)	9,013.01 6,176.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO SPRAY PAINT	New	800.00	650.00
2	LABOUR TO PANEL BEATING	New	600.00	400.00
3	LABOUR TO FOCUS HEADLAMP	New	80.00	30.00
4	LABOUR TO DISMANTLE AND REFIX UNDER CARRIAGEP ARTS	New	200.00	150.00
5	COMPUTERISED FRONT WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (S\$)			1,800.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >