

ASS. REC. BY:

REF:

U02/ 23002287/KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 835,204

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Tel. 671 relay 815,356-cv

Veh No:

SHF-299D

Yr Regn:

12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Pina

c.c.

1798

Colour

M. Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

473548

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDK B3FU803576481

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size:

F: Winsor

195/85R15

R:

Pailin

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

1

mm

L/Bal.

4

mm

L/Bal.

7

mm

D.O.A.

28/2/23

D.O.I.

3/3/2023

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Transportation

S + RS. SI

Fees

Others

Report Format:

Lump Sum / I.B.I. (\$

TOTAL

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68962623

Accident Reporting Number : 68862672

Date Generated : 03/03/2023

User ID : munsan

Section A - Accident Details

Registration Number	SHF299D
Case Reference Number	TAX/02/23/2069
Registration Date	14/12/17
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TIEN AH TEE
Type of Accident	Head to Rear
Accident Date and Time	28/2/23 2:45 PM
Accident Reported Date and Time	28/2/23 3:59 PM
Is Surveyor Required?	No
Surveyed by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24117773
Special Instruction to ARC, if any	BPM FRONT AND REAR
Prepared Date and Time	1/3/23 8:02 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,028.00	\$0.00
Total Spray Cost	\$2,772.00	\$0.00
Total Spare Part Cost	\$20,020.51	\$0.00
Total Other Cost	\$1,435.00	\$0.00
TOTAL COST	\$26,255.51	\$0.00
Lump Sum Total	\$26,250.00	\$0.00
Number of Repair Days	12.0	6 days
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	01/03/2023 8:50 AM	
Signature		x Kenneth Ho, e1kkawo.com
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68682623

Accident Reporting Number : 68682672

Date Generated : 03/03/2023

User ID : munsan

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR FRONT PORTION	\$676.00 200L	
O REPAIR REAR PORTION	\$1,352.00 500L	
total Labour	\$2,028.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY FRONT BUMPER	\$378.00 200L	
O RESPRAY FRONT SUPPORT PANEL	\$180.00 ?	
O RESPRAY REAR BUMPER	\$378.00 200L	
O RESPRAY REAR PANEL	\$180.00 ?	
O RESPRAY FLOOR CORNER PANEL LH	\$180.00 200L X	
O RESPRAY TAIL GATE	\$378.00 ?	
O RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00 150L	
O RESPRAY REAR SPOILER	\$180.00 X	
O RESPRAY FUEL LID COVER	\$180.00 X	
O RESPRAY REAR FENDER LH	\$378.00 X	
O RESPRAY REAR SPARE TYRE PANEL	\$180.00 X	
total Spray Painting & Panel Beating	\$2,772.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O WASH AND VACUUM	\$60.00 30L	
O CHECK WIRING AND SYSTEM FUNCTION	\$120.00 20L	
O APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00 X	
O TRANSFER REAR TAILGATE MECHANISM	\$120.00 X	
O REMOVE AND REFIX REAR WINDSCREEN	\$240.00 180L	
O PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$475.00 ?	
O TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00 30L	
O REPLACE SUNDRY PARTS	\$100.00 X	
total Other Costs	\$1,435.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5211947962	COVER, FR BUMPER	1.00	\$560.30	25.00	\$420.22	Replace	PHICRA ✓
		5211547050	SUPPORT, FR BUMPER RH	1.00	\$86.20	25.00	\$64.65	Replace	PHICRA 10.7 ✓
		5211647050	SUPPORT, FR BUMPER LH	1.00	\$86.20	25.00	\$64.65	Replace	PHICRA ✓
		5212747907	COVER, FR BUMPER RH	1.00	\$31.80	25.00	\$23.85	Replace	PHICRA X
		5212847906	COVER, FR BUMPER LH	1.00	\$31.80	25.00	\$23.85	Replace	PHICRA X
		5211447190	BRACKET, FR BUMPER	1.00	\$111.80	35.00	\$72.67	Replace	PHICRA ?
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	PHICRA X 3 45 ✓
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	PHICRA X 3 45 ✓
		5202147110	REINFORCEMENT FRONT UPPER	1.00	\$773.90	25.00	\$580.43	Replace	PHICRA ?
		5261147140	ABSORBER, FR BUMPER	1.00	\$85.90	25.00	\$64.43	Replace	PHICRA ?
		5210347010	EXTENSION SUB-ASSY, LH	1.00	\$129.90	25.00	\$97.43	Replace	PHICRA ?
		5210247020	EXTENSION SUB-ASSY, RH	1.00	\$129.90	25.00	\$97.43	Replace	PHICRA ?

SMRT Accident Vehicle Repair Estimates

60 Woodlands Industrial Park E4, Singapore 7577

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 03/03/2023

User ID : munsan

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5213247010	REINFORCEMENT FRONT LOWER	1.00	\$265.90	25.00	\$199.42	Replace	RX
		5261847090	ABSORBER, FR BUMPER LOWER	1.00	\$143.60	25.00	\$107.70	Replace	Th X
		5339547040	SEAL, HOOD TO FR END	1.00	\$55.80	25.00	\$41.85	Replace	
		7531047060	EMBLEM ASSY FRONT	1.00	\$98.70	25.00	\$74.03	Replace	Me ✓
		5311247240	GRILLE, RADIATOR	1.00	\$183.90	25.00	\$137.93	Replace	CRS ✓
		5310147080	GRILLE SUB-ASSY	1.00	\$374.40	25.00	\$280.80	Replace	?
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Me ✓
		5253550060	RETAINER, FR BUMPER, LH & RH	1.00	\$9.50	25.00	\$7.13	Replace	Me ✓
		5142047030	COVER ASSY, ENGINE	1.00	\$201.00	25.00	\$150.75	Replace	?
		5141047020	COVER ASSY, ENGINE UNDER CENTER SET	1.00	\$511.20	25.00	\$383.40	Replace	?
		8121047020	LAMP ASSY, FOG, RH	1.00	\$1,029.90	10.00	\$926.91	Replace	Sm X
		8122047020	LAMP ASSY, FOG, LH	1.00	\$1,029.90	10.00	\$926.91	Replace	Sm X
		8118547691	UNIT, HEADLAMP, LH	1.00	\$2,852.40	10.00	\$2,567.16	Replace	?
		8114547691	UNIT, HEADLAMP, RH	1.00	\$2,852.40	10.00	\$2,567.16	Replace	?
		8105647690	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1.00	\$1,039.90	10.00	\$935.91	Replace	Sm X
		8101647690	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	1.00	\$1,039.90	10.00	\$935.91	Replace	Sm X
		5320547900	SUPPORT S/A UPPER	1.00	\$408.50	25.00	\$306.38	Replace	?
		5321347050	SUPPORT, RADIATOR UPPER RH	1.00	\$85.20	25.00	\$63.90	Replace	X
		5321447050	SUPPORT, RADIATOR UPPER LH	1.00	\$85.20	25.00	\$63.90	Replace	X
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.17	Replace	Buc/CRS ✓
		5202347030	REAR BUMPER REINFORCEMENT	1.00	\$360.10	25.00	\$270.08	Replace	?
		5246247030	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	25.00	\$6.45	Replace	Me ✓
		5246247020	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	25.00	\$6.45	Replace	Me ✓
		5246247010	PAD, RR BUMPER, RH & LH, 3	2.00	\$4.30	25.00	\$6.45	Replace	Me ✓
		5246147010	PAD, RR BUMPER, CTR	1.00	\$2.50	25.00	\$1.88	Replace	Me ✓
		5219147030	SEAL, RR BUMPER ARM, RH & LH	1.00	\$12.30	25.00	\$9.23	Replace	?
		5259968030	STOPPER, RR BUMPER, RH & LH	1.00	\$4.80	25.00	\$3.60	Replace	?
		5257547040	RETAINER, RR BUMPER, RH	1.00	\$127.40	25.00	\$95.55	Replace	Sm X
		5257647040	RETAINER, RR BUMPER, LH	1.00	\$127.40	25.00	\$95.55	Replace	DR ✓
		5259147050	SEAL, RR BUMPER, RH	1.00	\$95.50	25.00	\$71.63	Replace	?
		5259247040	SEAL, RR BUMPER, LH	1.00	\$95.50	25.00	\$71.63	Replace	?
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Me ✓
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace	Me ✓
		5256547900	FILLER, RR BUMPER, RH	1.00	\$168.60	25.00	\$126.45	Replace	Sm X
		5256547900	FILLER, RR BUMPER, LH	1.00	\$168.60	25.00	\$126.45	Replace	My CRS ✓
		5216947020	COVER, GUARD RR BUMPER LOWER	1.00	\$18.70	25.00	\$12.52	Replace	?
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	DR ✓
		8999730100	ANTENNA, ELECTRICAL KEY	1.00	\$78.00	25.00	\$58.50	Replace	?

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 03/03/2023

User ID : munsan

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		9018906029	REAR BUMPER GROMMET SCREW	1.00	\$2.20	25.00	\$1.65	Replace	Sn X
		8155147281	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$489.00	10.00	\$440.10	Replace	Sn X
		8156147151	LENS & BODY, REAR COMBINATION LAMP, LH	1.00	\$489.00	10.00	\$440.10	Replace	cm ✓
		8158147010	LENS & BODY ASSY, RR BUMPER, RH	1.00	\$544.40	10.00	\$489.96	Replace	Sn X
		8159147010	LENS & BODY ASSY, RR BUMPER, LH	1.00	\$544.40	10.00	\$489.96	Replace	?
		8149747020	COVER, REAR COMBINATION LAMP, RH	1.00	\$69.90	25.00	\$52.43	Replace	Sn X
		8149847020	COVER, REAR COMBINATION LAMP, LH	1.00	\$69.90	25.00	\$52.43	Replace	?
		5839947030	COVER, REAR FLOOR UNDER, LH	1.00	\$261.60	25.00	\$196.20	Replace	?
		5839847050	COVER, REAR FLOOR UNDER, RH	1.00	\$189.20	25.00	\$141.90	Replace	Sn X
		6625947010	COVER, REAR FLOOR UNDER CENTER	1.00	\$249.10	25.00	\$186.83	Replace	?
		6160247160	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$943.10	25.00	\$707.33	Replace	R X
		6563847060	LINER, REAR FENDER, LH	1.00	\$151.10	25.00	\$113.32	Replace	Sn X
		7735047050	LID ASSY, FUEL FILLER OPENING	1.00	\$164.10	25.00	\$123.07	Replace	Sn X
			STICKER PETROL ONLY	1.00	\$7.80	0.00	\$7.80	Replace	Sn X
		6700547440	TAIL GATE PANEL SUB-ASSY, BACK DOOR	1.00	\$1,238.40	25.00	\$928.80	Replace	R X
		6788147050	TAIL GATE WEATHERSTRIP, BACK DOOR	1.00	\$402.50	25.00	\$301.88	Replace	AT ✓
		5611750140	TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1.00	\$31.10	25.00	\$23.33	Replace	Sn ✓
		7680147110A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1.00	\$992.30	25.00	\$744.22	Replace	cm ✓
		7544147090	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1.00	\$59.10	25.00	\$44.33	Replace	Sn ✓
		7544247130	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1.00	\$59.10	25.00	\$44.33	Replace	Sn ✓
		6810547291	TAIL GATE GLASS SUB-ASSY, BACK DOOR	1.00	\$1,795.00	25.00	\$1,346.25	Replace	Sn X
		6480147031	TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1.00	\$821.20	25.00	\$615.90	Replace	Shatter ✓
			SEALANT W/SCREEN (3PCS)	3.00	\$37.00	0.00	\$111.00	Replace	Sn ✓
		6881047061	TAIL GATE BACK DOOR HINGE ASSY, RH & LH	2.00	\$66.20	25.00	\$99.30	Replace	R X
		6935047050	TAIL GATE LOCK ASSY, BACK DOOR	1.00	\$505.50	10.00	\$454.95	Replace	R X
		6932147010	TAIL GATE LOCK COVER, BACK DOOR	1.00	\$32.70	25.00	\$24.53	Replace	Sn X
		7540348010	EMBLEM SUB-ASSY REAR	1.00	\$77.40	25.00	\$58.05	Replace	Sn ✓
		7608547916	SPOILER SUB-ASSY, REAR	1.00	\$1,704.20	25.00	\$1,278.15	Replace	Sn X
		8100847030	LAMP SET, STOP CENTER	1.00	\$207.90	10.00	\$187.11	Replace	Sn X
			STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Sn ✓

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 03/03/2023

User ID : munsan

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	<i>mu</i>
		5830747090	END PANEL SUB-ASSY. BODY LOWER BACK	1.00	\$707.10	25.00	\$530.33	Replace	<i>R ?</i>
		5831147130	SPARE TYRE PANEL . PAN, REAR FLOOR	1.00	\$630.30	25.00	\$472.72	Replace	<i>R X</i>
			SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	<i>nnx</i>
Total					\$30,525.50		\$25,062.64		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

*Not Notion
11/2/23*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey must be on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary charges must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	01/03/2023 13:00 (SGT)
Reported by	Driver
Date of Accident	28/02/2023 14:45 (SGT)
Exact Location of Accident	CTE, Singapore
Additional Location Information	CTE TOWARDS BUKIT TIMAH
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF299D
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-22099115MFSH

DRIVER

Name of Driver	TIEN AH TEE
NRIC No	SXXXX629J
Date Of Birth	19/04/1956
Occupation	Outdoor

IMPORTANT NOTICE

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

[Signature]

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]

28.2.2023.

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

	CTE A - SHF299D B - YP178R.. C - SHD633S.X D - unknown E - unknown
--	--