

Century Motors Pte Ltd (Co.Reg.No:192800002R)

2 Pandan Crescent, Inchape Centre Level 10

Singapore 128462

Tel: 66311118 Email: nicola.gear@inchape.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2003930241-01	Date of Loss:	27/02/2023
Vehicle Reg. No.:	SMX4587S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LAM FAIR FONG		
Driver:	NEO SZU WAN AARON (LIANG SIYUAN)		

Make/Model:	HYUNDAI ELANTRA, 1.6 AD (A)	Vehicle Reg. Date:	13/02/2018
Vehicle Colour:	BEIGE		
Engine No:	G4FGJU134373	Chassis No:	KMHD841CMJU628483
Odometer:	79635 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	7

Present Location: CENTURY MOTORS PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	6,006.00
Miscellaneous Items	215.00
Labour	2,700.00
Paintwork Labour	0.00
Towing	0.00
	Gross Total (S\$) 8,921.00
	+ GST 8.00% (S\$) 713.68
	Nett Amount (S\$) 9,634.68

This claim is handled by: LOH CHEN KHUAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 02 Mar 2023)**Parts:** 143 HYUNDAI ELANTRA 1.6 AD (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Century Motors Pte Ltd/SMX4587S/02/03/2023 14:22**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN	0.00	0.00	*600.00 F
2	1		*FRONT WINDSCREEN MOULDING	0.00	0.00	*70.00 F
3	1		*HEAD LAMP LH	0.00	0.00	*540.00 F
4	1		*HEAD LAMP SUPPORT LH	0.00	0.00	*20.00 F
5	1		*FRONT BONNET	0.00	0.00	*750.00 F
6	1		*BONNET LOCK	0.00	0.00	*90.00 F
7	1		*BONNET HINGE LH	0.00	0.00	*45.00 F
8	1		*BONNET HINGE RH	0.00	0.00	*45.00 F
9	1		*FRONT BUMPER	0.00	0.00	*420.00 F
10	1		*FRONT BUMPER INNER BRACKET LH	0.00	0.00	*25.00 F
11	1		*FRONT BUMPER UPPER BRACKET LH	0.00	0.00	*25.00 F
12	1		*FRONT BUMPER SIDE RETAINER	0.00	0.00	*25.00 F
13	1		*FRONT BUMPER SPONGE	0.00	0.00	*90.00 F
14	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*230.00 F
15	1		*FRONT BUMPER AIR INTAKE COVER LH	0.00	0.00	*20.00 F
16	1		*FRONT FENDER LH	0.00	0.00	*420.00 F
17	1		*FRONT FENDER INNER SHIELD LH	0.00	0.00	*60.00 F
18	1		*FRONT FOG LAMP LH	0.00	0.00	*130.00 F
19	1		*FRONT FOG LAMP COVER LH	0.00	0.00	*60.00 F
20	1		*FRONT GRILLE	0.00	0.00	*420.00 F
21	1		*FRONT SUPPORT PANEL	0.00	0.00	*460.00 F
22	1		*RADIATOR	0.00	0.00	*300.00 F
23	1		*CONDENSER	0.00	0.00	*340.00 F
24	1		*AIR INTAKE DUCT	0.00	0.00	*60.00 F
25	1		*AIR FILTER HOUSING ASSY	0.00	0.00	*125.00 F
26	1		*FUSE BOX UPPER COVER	0.00	0.00	*50.00 F
27	1		*SIDE MEMBER BRACKET LH	0.00	0.00	*40.00 F

F=Franchise part.

Sub Total (S\$)	5,460.00
+ Margin on L,N Items 10.00% (S\$)	546.00
Total Parts (S\$)	6,006.00

Century Motors Pte Ltd/SMX4587S/02/03/2023 14:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	AIRCOND GAS	60.00
2	1	FRONT BUMPER CLIPS	30.00
3	1	FRONT NUMBER PLATE & HOLDER	35.00
4	1	RADIATOR COOLANT	30.00
5	1	WINDSCREEN SEALANT	60.00
Sub Total (S\$)			215.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	LABOUR FOR PANEL BEATING	New	1,400.00
2	LABOUR FOR SPRAY PAINTING	New	1,200.00
3	TO REMOVE & REFIT FRONT WINDSCREEN	New	100.00
Gross Labour Cost (S\$)			2,700.00

Century Motors Pte Ltd/SMX4587S/02/03/2023 14:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >