

(08/11/13) wef  
ASS. REC. BY: /

REF: CS6/A1823002288/Hvy3

# Desk Top Survey. ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD  TP  WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: **TBA**

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: **\$63K**

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS \_\_\_\_\_

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: **SLW47584** Yr Regn: **13/2/2018**

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: **Hyundai Elantra GLS** c.c. **1591**

Colour: **Beige** A/C: **Insured / Std / NI / NA**

Sp. Reading: **79635** T/Radio: **Insured / Std / NI / NA**

Eng/No: \_\_\_\_\_

C/No: **KMHD841CM04628483**

Gen. Cond: Good /  Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim /  STD A/Rim or

Tyre Size: F: \_\_\_\_\_ ?

R: \_\_\_\_\_ ?

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or ?

Front \_\_\_\_\_ Rear \_\_\_\_\_ ?

R/Bal. \_\_\_\_\_ mm ? R/Bal. \_\_\_\_\_ mm ?

L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm

D.O.A. **27/2/2023** D.O.I. \_\_\_\_\_

Survey held at **Desk Top Survey.**

Des. of Damages:  Frt / Rear / O/S /  N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Rebate/PV \$27,797
	Net Value \$35,203.

Date/Time, File Pass to?  : Preli. Report  : Final Report

1) \_\_\_\_\_ Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format : \_\_\_\_\_

Lump Sum / I.B.!: (\$ \_\_\_\_\_ )

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_ )  : Interview (\$ \_\_\_\_\_ )  : Tech. Invs (\$ \_\_\_\_\_ )  : Weekend (\$ \_\_\_\_\_ )

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS, SI \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL \_\_\_\_\_

> Back to OneMotoring

D.O.A. ? 27/2/2023  
Bal. : 4 yrs 11.5 mths.  
M.V. : \$63,000...

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	009G
Vehicle Details	
Vehicle No.:	SLW4758H
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Mar 2023
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT (AMS)
Primary Colour:	Beige
Manufacturing Year:	2018
Engine No.:	G4FGJU134373
Chassis No.:	KMHD841CMJU628483
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$11,583.00
Original Registration Date:	13 Feb 2018
First Registration Date:	13 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$11,583.00 ✓
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Feb 2028 //
PARF Rebate Amount:	\$8,108.00 5791
Intended COE Rebate Details	
COE Expiry Date:	12 Feb 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$40,000.00
COE Rebate Amount:	\$19,689.00
<b>Total Rebate Amount:</b>	<b>\$27,797.00</b>

The information contained herein is correct as at 06 Mar 2023

OK

12,580  
12,470  
12,460  
11,900

11,530

## Century Motors Pte Ltd (Co.Reg.No:192800002R)

2 Pandan Crescent, Inchage Centre Level 10  
Singapore 128462

Tel: 66311118 Email: nicola.gear@inchape.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2003930241-01	Date of Loss:	27/02/2023
Vehicle Reg. No.:	<del>SMX4587S</del> SLW 4758H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LAM FAIR FONG		
Driver:	NEO SZU WAN AARON (LIANG SIYUAN)		

Make/Model:	HYUNDAI ELANTRA, 1.6 AD (A)	Vehicle Reg. Date:	13/02/2018
Vehicle Colour:	BEIGE		
Engine No:	G4FGJU134373	Chassis No:	KMHD841CMJU628483
Odometer:	79635 KM		

Paint Type:  
Total Loss?  
Est. Duration of Repair  
(day)

NO  
7

Present Location: CENTURY MOTORS PTE LTD (HQ)

**COST OF CLAIMS**

	<b>Amount</b>
Parts	6,006.00
Miscellaneous Items	215.00
Labour	2,700.00
Paintwork Labour	0.00
Towing	0.00
	<b>Gross Total (\$)</b> 8,921.00
	<b>+ GST 8.00% (\$)</b> 713.68
	<b>Nett Amount (\$)</b> 9,634.68

This claim is handled by: LOH CHEN KHUAN

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Mar 2023)

Parts: 143 HYUNDAI ELANTRA 1.6 AD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Century Motors Pte Ltd/SMX4587S/02/03/2023 14:22

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN	0.00	0.00	*600.00 F CUT
2	1		*FRONT WINDSCREEN MOULDING	0.00	0.00	*70.00 F NEC
3	1		*HEAD LAMP LH	0.00	0.00	*540.00 F CRU
4	1		*HEAD LAMP SUPPORT LH	0.00	0.00	*20.00 F ?
5	1		*FRONT BONNET	0.00	0.00	*750.00 F BUC
6	1		*BONNET LOCK	0.00	0.00	*90.00 F BT
7	1		*BONNET HINGE LH	0.00	0.00	*45.00 F BT
8	1		*BONNET HINGE RH	0.00	0.00	*45.00 F BT
9	1		*FRONT BUMPER	0.00	0.00	*420.00 F CRA
10	1		*FRONT BUMPER INNER BRACKET LH	0.00	0.00	*25.00 F ?
11	1		*FRONT BUMPER UPPER BRACKET LH	0.00	0.00	*25.00 F ?
12	1		*FRONT BUMPER SIDE RETAINER	0.00	0.00	*25.00 F DIS
13	1		*FRONT BUMPER SPONGE	0.00	0.00	*90.00 F ?
14	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*230.00 F ?
15	1		*FRONT BUMPER AIR INTAKE COVER LH	0.00	0.00	*20.00 F ?
16	1		*FRONT FENDER LH	0.00	0.00	*420.00 F XR
17	1		*FRONT FENDER INNER SHIELD LH	0.00	0.00	*60.00 F ?
18	1		*FRONT FOG LAMP LH	0.00	0.00	*130.00 F ?
19	1		*FRONT FOG LAMP COVER LH	0.00	0.00	*60.00 F ?
20	1		*FRONT GRILLE	0.00	0.00	*420.00 F CUT
21	1		*FRONT SUPPORT PANEL	0.00	0.00	*460.00 F BT
22	1		*RADIATOR	0.00	0.00	*300.00 F ?
23	1		*CONDENSER	0.00	0.00	*340.00 F ?
24	1		*AIR INTAKE DUCT	0.00	0.00	*60.00 F ?
25	1		*AIR FILTER HOUSING ASSY	0.00	0.00	*125.00 F ?
26	1		*FUSE BOX UPPER COVER	0.00	0.00	*50.00 F ?
27	1		*SIDE MEMBER BRACKET LH	0.00	0.00	*40.00 F ?

F=Franchise part.

Sub Total (S\$)	5,460.00
+ Margin on L,N Items 10.00% (S\$)	+ 546.00
<b>Total Parts (S\$)</b>	<b>6,006.00</b>

Century Motors Pte Ltd/SMX4587S/02/03/2023 14:22. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

### Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	AIRCOND GAS	60.00?
2	1	FRONT BUMPER CLIPS	30.00
3	1	FRONT NUMBER PLATE & HOLDER	35.00
4	1	RADIATOR COOLANT	30.00
5	1	WINDSCREEN SEALANT	60.00
Sub Total (\$\$)			215.00

### Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	LABOUR FOR PANEL BEATING	New	1,400.00 600
2	LABOUR FOR SPRAY PAINTING	New	1,200.00 700
3	TO REMOVE & REFIT FRONT WINDSCREEN	New	100.00
Gross Labour Cost (\$\$)			2,700.00

Century Motors Pte Ltd/SMX4587S/02/03/2023 14:22. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR 5 DAYS

- NOT AUTHORISE
- EXCESS ? TBA
- P/P OR I/S REPAIR
- SURVEY BY EDWARD TEL: 62563561
- RESURVEY BEFORE PAINT FOR P/P REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: