

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 06 Mar 2023

Preliminary Advice

Vehicle No	: SLW4758H	Accident Date	: 27/02/2023
Make	: HYUNDAI ELANTRA	Policy No.	: SP2003930241-01
Assignment Date	: 02/03/2023	Excess	: S\$0.00
Date of Inspection	: DESKTOP SURVEY	Est. Duration of Repair	: 5
Inspection At	: CENTURY MOTORS PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,921.00
Revised Amount	:S\$	5,301.50
Check Items (Estimated)	:S\$	1,822.50
Total	:S\$	7,124.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	63,000.00
COE / PARF Rebate	:S\$	27,797.00
Salvage Value	:S\$	
Margin for Repair	:S\$	35,203.00

Remarks (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. (X) Other comments : Lump Sum Repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .