

Century Motors Pte Ltd (Co.Reg.No:192800002R)

2 Pandan Crescent, Inchape Centre Level 10

Singapore 128462

Tel: 66311118 Email: nicola.gear@inchape.com.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2003930241-01	Date of Loss:	27/02/2023
Vehicle Reg. No.:	SMX4587S SLW 4758H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LAM FAIR FONG		
Driver:	NEO SZU WAN AARON (LIANG SIYUAN)		

Make/Model:	HYUNDAI ELANTRA, 1.6 AD (A)	Vehicle Reg. Date:	13/02/2018
Vehicle Colour:	BEIGE		
Engine No:	G4FGJU134373	Chassis No:	KMHD841CMJU628483
Odometer:	79635 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	7

Present Location:	CENTURY MOTORS PTE LTD (HQ)
-------------------	-----------------------------

COST OF CLAIMS

	Amount
Parts	6,006.00
Miscellaneous Items	215.00
Labour	2,700.00
Paintwork Labour	0.00
Towing	0.00
	<hr/>
	Gross Total (S\$) 8,921.00
	+ GST 8.00% (S\$) 713.68
	<hr/>
	Nett Amount (S\$) 9,634.68

This claim is handled by: LOH CHEN KHUAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Mar 2023)

Parts: 143 HYUNDAI ELANTRA 1.6 AD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Century Motors Pte Ltd/SMX4587S/02/03/2023 14:22

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN	0.00	0.00	*600.00 F ^{CUT}
2	1		*FRONT WINDSCREEN MOULDING	0.00	0.00	*70.00 F ^{NEC}
3	1		*HEAD LAMP LH	0.00	0.00	*540.00 F ^{CRU}
4	1		*HEAD LAMP SUPPORT LH	0.00	0.00	*20.00 F [?]
5	1		*FRONT BONNET	0.00	0.00	*750.00 F ^{BUC}
6	1		*BONNET LOCK	0.00	0.00	*90.00 F ^{BT}
7	1		*BONNET HINGE LH	0.00	0.00	*45.00 F ^{BT}
8	1		*BONNET HINGE RH	0.00	0.00	*45.00 F ^{BT}
9	1		*FRONT BUMPER	0.00	0.00	*420.00 F ^{CRA}
10	1		*FRONT BUMPER INNER BRACKET LH	0.00	0.00	*25.00 F [?]
11	1		*FRONT BUMPER UPPER BRACKET LH	0.00	0.00	*25.00 F [?]
12	1		*FRONT BUMPER SIDE RETAINER	0.00	0.00	*25.00 F ^{DIS}
13	1		*FRONT BUMPER SPONGE	0.00	0.00	*90.00 F [?]
14	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*230.00 F [?]
15	1		*FRONT BUMPER AIR INTAKE COVER LH	0.00	0.00	*20.00 F [?]
16	1		*FRONT FENDER LH	0.00	0.00	*420.00 F ^{XR}
17	1		*FRONT FENDER INNER SHIELD LH	0.00	0.00	*60.00 F [?]
18	1		*FRONT FOG LAMP LH	0.00	0.00	*130.00 F [?]
19	1		*FRONT FOG LAMP COVER LH	0.00	0.00	*60.00 F [?]
20	1		*FRONT GRILLE	0.00	0.00	*420.00 F ^{CUT}
21	1		*FRONT SUPPORT PANEL	0.00	0.00	*460.00 F ^{BT}
22	1		*RADIATOR	0.00	0.00	*300.00 F [?]
23	1		*CONDENSER	0.00	0.00	*340.00 F [?]
24	1		*AIR INTAKE DUCT	0.00	0.00	*60.00 F [?]
25	1		*AIR FILTER HOUSING ASSY	0.00	0.00	*125.00 F [?]
26	1		*FUSE BOX UPPER COVER	0.00	0.00	*50.00 F [?]
27	1		*SIDE MEMBER BRACKET LH	0.00	0.00	*40.00 F [?]

F=Franchise part.

Sub Total (S\$)	5,460.00
+ Margin on L,N Items 10.00% (S\$)	+ 546.00
Total Parts (S\$)	6,006.00

Century Motors Pte Ltd/SMX4587S/02/03/2023 14:22. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	AIRCOND GAS	60.00?
2	1	FRONT BUMPER CLIPS	30.00
3	1	FRONT NUMBER PLATE & HOLDER	35.00
4	1	RADIATOR COOLANT	30.00
5	1	WINDSCREEN SEALANT	60.00
Sub Total (S\$)			215.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	LABOUR FOR PANEL BEATING	New	1,400.00 600
2	LABOUR FOR SPRAY PAINTING	New	1,200.00 700
3	TO REMOVE & REFIT FRONT WINDSCREEN	New	100.00
Gross Labour Cost (S\$)			2,700.00

Century Motors Pte Ltd/SMX4587S/02/03/2023 14:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR 5 DAYS

- NOT AUTHORISE
- EXCESS ? TBA
- P/P OR H/S REPAIR
- SURVEY BY EDWARD TEL: 62563561
- RESURVEY BEFORE PAINT FOR P/P REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: